| Submit 3 Copies To Appropriate District Office District I | orace of 1 | New Mexico nd Natural Resources | 3 | | Form C- Revised March 25. | | |
|--|------------------------------|------------------------------------|----------------|-------------------------|------------------------------|---------|--|
| 1625 N. French Dr., Hobbs, NM 87240 District II | | | | L API NO. | | | |
| 811 South First, Artesia, NM 87210 | OIL CONSERVATION DIVISION | | 1 | 30-025-29980 | | | |
| District III | | uth Pacheco | 5. Inc | licate Type of | Lease | | |
| 1000 Rio Brazos Rd., Aztec, NM 87410 District IV | | , NM 87505 | | STATE | | | |
| 2040 South Pacheco, Santa Fe, NM 8750 | 5 | | 6. Sta | te Oil & Gas | | | |
| | | | | | 020 | | |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | | | | Jnit Agreement Name: | | |
| 1. Type of Well: | | | | Byers | | | |
| Oil Well 🕱 Gas Well 🗌 Other | | | | | | | |
| 2. Name of Operator | | | | II No | • | | |
| Gruy Petroleum Management Co. | | | | 8. Well No. | | | |
| 3. Address of Operator | | | 9 Por | 9. Pool name or Wildcat | | | |
| P.O. Box 140907 Irving, Texas 75014-0907 | | | | Shipp Strawn | | | |
| 4. Well Location | | | | Strawn | | | |
| Unit Letter I | | | | | | | |
| Section 3 | Township 1 | 75 Range 37 | 'E NMPI | М | Carl | | |
| | 10. Elevation (Show w | | GR etc. | VI | County Lea | | |
| | ×× | 3764 'GR | , | | | | |
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | | | | | | | |
| NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: | | | | | | | |
| PERFORM REMEDIAL WORK | _ | | | | | | |
| | | | | | ALTERING CASING | | |
| | CHANGE PLANS | | RILLING OPN | IS. | PLUG AND | | |
| PULL OR ALTER CASING | MULTIPLE COMPLETION | CASING TEST CEMENT JOB | AND | | ABANDONMENT | | |
| OTHER: | | | | | | | |
| 12 Describe Proposed on Control | | OTHER: | | | | | |
| 12. Describe Proposed or Complete | eq Operations (Clearly state | all pertipent details | nd aire martin | | | _ | |

 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Gruy Petroleum Management Co. respectfully request approval to perform the work on the well as per the following procedure.

| I hereby certify that the information above is true and | complete to the best of my knowledge and belief. | | |
|---|--|---------------|--------------------|
| SIGNATURE KOM (1101 | Ully TITLE Sr. Regulatory Analyst | DATE | 10-14-2002 |
| Type or print name Don Aldridge | | | |
| (This space for State was) | GARY W LOUP (60 SY | Telephone No. | 469-420-2728 |
| APPROVED BY Conditions of approval, if any: | GARY W. WINK OC FIELD REPORTS | DATE_ | CT <u>2 8 2002</u> |

RECOMMENDED WORKOVER PROCEDURE BYERS #1 SHIPP FIELD LEA COUNTY, NEW MEXICO

WELL DATA

| SPUD DATE: | 7/18/87 |
|---------------------|---|
| PERM. ZERO PT.: | GL=3764.1' |
| TOTAL DEPTH: | 11,769' |
| SURFACE CSG: | 13-3/8", 48#, H-40 @ 425' |
| INTER CSG: | 8-5/8", 28#, S-80 @ 4210' |
| PROD CSG: | 5-1/2", 17#, N-80 @ 11,769' |
| OPEN PERFS : | none |
| SHUT-OFF PERFS: | Strawn 11415-20, 11432-62, 11467-505, 11510-36, 11547-51' |
| | Atoka 11602-11613' |
| TBG: | None |
| PKR: | None |
| OTHER: | CIBP @ 11,380' |
| | CIBP w/ 35' cmt @ 11,515' |

OBJECTIVE: Recommending re-perforating, acidizing and testing the Strawn.

**** SAFETY IS TOP PRIORITY ****

PROCEDURE:

- 1. MIRU wellservice rig. ND WH. NU BOP's and test.
- 2. PU & RIH w/ bit & scpr on 2-7/8", N-80 workstring to PBTD +/- 11380'. Attempt to circ hole. POH.
- 3. PU & RIH w/ pkr to CIBP. Test CIBP. Isolate csg leaks.

NOTE: Csg inspection log showed extreme pitting w/ possible holes @ 6115, 6250-6294, 6410, 6966 and 7157'. Can pump-in 2 bpm @ 200 psi.

C

- 4. Evaluate csg leaks as follows:
 - a. If holes can be isolated, sqz and drill out.
 - b. If specific leaks cannot be identified, continue w/ procedure to test well to evaluate for liner.
- 5. DO CIBP @ 11380'.
- 6. MIRU e-line. Install lubricator. If unable to locate openhole logs from OCD, run CNL/GR/CCL log from PBTD to 4200' and fax in for determination of perfs. RIH w/ GR/CCL & run strip log for correlation.

Byers #1

ĩ

- 7. RIH w/ csg guns and re-perf Strawn 11415-20, 11432-62, 11467-505, 11510-36, 11547-51, 2 JSPF. RD e-line.
- 8. PU & RIH w/ 10k stimulation pkr on 2-7/8" tbg to 11350'. Load annulus and pressure to 500 psi if possible.
- 9. MIRU Petroplex. Acidize well w/ 10,000 gals 15% FE/AS-2X HCL acid as follows:
 - a. Load tbg and EIR w/ 2% KCL
 - b. Pump 2000 gals acid
 - c. Pump 500 gals gelled saturated brine w/ 1000# 50/50 GRS & 100 mesh salt mix
 - d. Pump 3000 gals acid
 - e. Pump 500 gals gelled saturated brine w/ 1000# 50/50 GRS & 100 mesh salt mix
 - f. Pump 5000 gals acid
 - g. Flush & overflush w/ 5000 gals 2% KCL wtr

Adjust 2nd blk as necessary. Pump at 5-8 bpm w/ max pressure of 8000 psi.

- 10. RU swab. Swab back acid water.
- 11. Rls pkr, Lower, Tag PBTD and POH laying down workstring.
- 12. RIH w/ pumping setup. Run pkr to pump below pkr if csg was not repaired.
 - 13. ND BOP's. NU wellhead.
 - 14. RIH w/ 1.25" insert pump on 76 rod string w/ sinker bars. Run RODSTAR for rod string design.
 - 15. Start well pumping. RD & RR.
 - 16. Evaluate well for additional work.

GRUY PETROLEUM MANAGEMENT CO.



GRUY PETROLEUM MANAGEMENT CO.



4