

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. OIL CONS. COMMISSION
P.O. BOX 1980
HOBBS, NEW MEXICO 88240
Expires: March 31, 1993

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reenter to a different formation
Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE BUREAU OF LAND MGMT.
HOBBS, NM.

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Harvey E. Yates Company

3. Address and Telephone No.

P.O. Box 1993, Roswell, NM 88202 1-505-623-6601

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

E, 1650' FNL & 990' FWL
SEC. 12, T-18S, R-32E

5. Lease Designation and Serial No.

NM-40456

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

CHEVRON 12 FEDERAL # 2

9. API Well No.

30-025-30028

10. Field and Pool, or Exploratory Area

YOUNG BONE SPRING, N.

11. County or Parish, State

LEA CO., NM

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other P&A

TYPE OF ACTION

- ☐ Change in Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. SET CIBP 6720' w/ 50' CMT ON TOP.
2. ATTEMPT TO CUT 5 1/2" CASING INSIDE 8 5/8" (15' ABOVE 8 5/8" SHOE) & PULL CASING.
3. PUMP 150' PLUG AT CUTOFF (50' IN & 100' OUT) STUB & TAG.
4. IF CASING NOT FREE AT CUT THEN PUMP 150' PLUG FROM 2965' TO 2815' & TAG.
5. MAKE ADDITIONAL CUT AND RECOVER AS MUCH 5 1/2" AS POSS.
6. IF CUT IS OTHER THAN ABOVE THEN PUMP 100' PLUG ACROSS STUB, (50' IN & 50' OUT).
7. PUMP 100' CMT PLUG ACROSS SURFACE SHOE (FROM 450' TO 350').
8. CUT OFF WELL HEAD. PUMP 50' CMT PLUG AT SURFACE & INSTALL DRY HOLE MARKER.
9. BACKFILL ALL PITS, CLEAN LOC. & REHAB.

CALL BLM-HOBBS OFFICE 24 HOURS PRIOR TO PLUGGING. 1-505-393-3612

PLUGGING OF WELL WILL COMMENCE WITHIN 90 DAYS OR AS SOON AS PLUGGING CREW IS AVAILABLE.

ABOVE APPROVED BY SHANNON SHAW-BLM CARLSBAD, 1-6-95. rfn

14. I hereby certify that the foregoing is true and correct

Signed Ray F. Nokes Title

PROD. MGR./ ENG.

Date 1/6/95

(This space for Federal or State office use)

Approved by Orig. Signed by Shannon J. Shaw

Title BLM CARLSBAD DISTRICT ENGINEER

Date 1/13/95

Conditions of approval, if any:

RECEIVED

JAN 14 1966
OCD HOLDING
OFFICE