

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-30148
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-654

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name State MTS "X"
2. Name of Operator Amerind Oil Company Limited Partnership	8. Well No. 1
3. Address of Operator 415 W Wall Suite 500, Midland Texas 79701	9. Pool name or Wildcat Shipp Strawn
4. Well Location: H: I 2310 South 334 East Unit Letter: SL: I : 1830 Feet From The South 660 Feet From The East Line Section 2 Township 17S Range 37E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3746' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 11,800' cap w/35' of cmt.
2. Set 100' cmt plug @ 5-1/2" csg stub @ approx. 10,000'. 50' in 50' out. Tag
3. Set 100' cmt plug @ 9037'.
4. Set 100' cmt plug @ 5303'.
5. Set 100' cmt plug @ 4500' @ 8-3/5" csg shoe. 50'in 50' out.
6. Set 100' cmt plug @ 2127'.
7. Set 10 sx cmt plug @ surface & install P & A marker.
8. Load hole w/10# salt gel.

THIS IS A COPY OF THE RECORD OF
PROPOSED OPERATIONS FOR THE CIBP
TO BE APPROVED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James E. Yeley TITLE Agent DATE March 25, 1992
TYPE OR PRINT NAME James E. Yeley TELEPHONE NO. 915/682-8217

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE MAR 31

CONDITIONS OF APPROVAL, IF ANY: