m 3160-3 ovember 1983) merly 9-331C)	IL.UNIT	ED STATES OF-YHE INTER	(Other instru reverse a		Budget Bureau Expires August	31, 1985	
					5. LEASE DEGIGRATION	AND GERIAL NO.	
		LAND MANAGEMEN	A		NM-32410	B OR TRIRE NAME	
APPLICATION	N FOR PERMIT	O7DRIELS DEEPE	N, OR PLUG	BACK			
TYPE OF WORK		DEEPEN	PLUG BA	CK 🖾	7. UNIT AGREEMENT P	AWB.	
TIPE OF WELL	ELL XX OTHER		NGLE XX MULTI		8. FARM OR LEASE NA	ж з	
VELL W			Shinnery Federal				
Moridian Oil	Inc				9. WELL NO.		
<u>Moridian Oil</u> Do ites of Off EATOR 21 Desta Dri	1 19. FIELD AND FOOL, OR WILDCAT Wildcate (Queen)						
LOCATION OF WELL (B	eport location clearly and	in accordance with any S			Wildcatd (Queen) 11. SBC., T., B., M., OR BLK. AND SURVEY OR AREA Sec. 13, T-18-S, R-32-H		
1980'	FS & WL, Sec.	13, T-18-S, R-32	2-Е				
At proposed prod. so	De						
DISTANCE IN MILES	AND DIRECTION FROM NEA	REST TOWN OR POST OFFIC			12. COUNTY OR PARISH 18. STATE		
	ith of Maljamar,				Lea	NM	
DISTANCE FROM PROP LOCATION TO NEARER	USED*	16. NO	. OF ACRES IN LEASE	17. NO.	OF ACRES ASSIGNED HIS WELL		
PROPERTY OR LEASE	LINE, FT. 1 g. unit line, if any)	980' 8	-				
DISTANCE FROM PROFOSED LOCATION®			19. PROPOSED DEPTH 4950'		20. ROTARY OR CABLE TOOLS NA		
	nether DF, RT, GR, etc.)				22. APPROX. DATE W	VORK WILL START*	
3831' GR					11-7-88		
		PROPOSED CASING AN	D CEMENTING PROGR	AM			
SIZE OF HOLE	BIZE OF CABING	WEIGHT PER FOOT	SETTING DEPTH		QUANTITY OF CEM		
17 1/2"	13 3/8"	54.5#	383'		sx. Cl "C", C		
12 1/4"	9 5/8"	40#	2904		sx. Cl "C", C sx. Cl "H". T		
7 7/8"	$5 \frac{1}{2}$	17#	12,498	1/ynn	SX. LI D. IV		
/ //0	5 1/2	1.1.1		2505			
1. MIRU 2. RIH W	PU. POH w/rods & /cmt ret, sting	 & pmp. ND pmp te er & tbg. Set ro	l e. NU BOP. Ris et @ <u>+</u> 4950' &	e TAC & estab	POH w/tbg. lish pmp in ra	ate	
1. MIRU 2. RIH w & pre 3. MIRU Sting press Pull	PU. POH w/rods & /cmt ret, sting ss. cmt company. Sp into ret & so above pmp in p tbg up to 4552	 & pmp. ND pmp te er & tbg. Set ro ot 100 sx C1 "C gz off Delaware rocc. Sting out	 e. NU BOP. R1s et @ <u>+</u> 4950' & C" & 150 sx C1 perfs. Attemp of ret & rev	e TAC & estab "C" ne ot to ol excess	POH w/tbg. lish pmp in ra eat @ end o tl btain a 500# cmt out of t	ate bg. sqz bg.	
1. MIRU 2. RIH w & pre 3. MIRU Sting press Pull compa 4. MIRU	PU. POH w/rods & /cmt ret, sting ss. cmt company. Sp into ret & so above pmp in p tbg up to 4552 ny. POH. WL unit. RIH	A pmp. ND pmp te er & tbg. Set ro ot 100 sx C1 "C z off Delaware ress. Sting out 2' & spot 250 g w/csg guns & p	e. NU BOP. Rls et @ <u>+</u> 4950' & c" & 150 sx Cl perfs. Attemp of ret & rev gals 7 1/2% N perf Queen @	e TAC & estab "C" ne ot to ol excess EFE HC1 4542-45	POH w/tbg. lish pmp in ra eat @ end o tl btain a 500# cmt out of t acid. RDMO 552 w/2 JSPF	ate bg. sqz bg. cmt (21	
1. MIRU 2. RIH w & pre 3. MIRU Sting press Pull compa 4. MIRU holes 5. RIH	PU. POH w/rods & /cmt ret, sting ss. cmt company. Sp into ret & so above pmp in p tbg up to 4552 ny. POH. WL unit. RIH	A pmp. ND pmp te er & tbg. Set ro ot 100 sx C1 "C z off Delaware ress. Sting out 2' & spot 250 g w/csg guns & p	e. NU BOP. Rls et @ <u>+</u> 4950' & c" & 150 sx Cl perfs. Attemp of ret & rev gals 7 1/2% N perf Queen @	e TAC & estab "C" ne ot to ol excess EFE HC1 4542-45	POH w/tbg. lish pmp in ra eat @ end o tl btain a 500# cmt out of t acid. RDMO 552 w/2 JSPF	ate bg. sqz bg. cmt (21	
 MIRU RIH w & pre MIRU MIRU Sting press Pull compa MIRU holes RIH spot 	PU. POH w/rods & /cmt ret, sting ss. cmt company. Sp into ret & so above pmp in p tbg up to 4552 ny. POH. WL unit. RIH s). POH. RDMO WL w/trtg pkr, SN acid away. The PROFOSED PROGRAM : If to drill or deepen direction	k pmp. ND pmp te er & tbg. Set ro ot 100 sx C1 "C z off Delaware ress. Sting out 2' & spot 250 g w/csg guns & f unit. & tbg. Rev spot	e. NU BOP. R1s et @ <u>+</u> 4950' & " & 150 sx C1 perfs. Attemp of ret & rev gals 7 1/2% N perf Queen @ acid into tbg	e TAC & estab "C" ne t to ol excess EFE HC1 4542-45 & set p	POH w/tbg. lish pmp in rate eat @ end o the btain a 500# cmt out of the acid. RDMO 552 w/2 JSPF okr @ \pm 4440'.	ate bg. sqz bg. cmt (21 Pmp	
1. MIRU 2. RIH w & pre 3. MIRU Sting press Pull compa 4. MIRU holes 5. RIH spot	PU. POH w/rods & /cmt ret, sting ss. cmt company. Sp into ret & so above pmp in p tbg up to 4552 ny. POH. WL unit. RIH s). POH. RDMO WL w/trtg pkr, SN acid away. The PROFOSED PROGRAM : If to drill or deepen direction	& pmp. ND pmp te er & tbg. Set re ot 100 sx C1 "C iz off Delaware ress. Sting out 2' & spot 250 g w/csg guns & unit. & tbg. Rev spot	e. NU BOP. R1s et @ <u>+</u> 4950' & " & 150 sx C1 perfs. Attemp of ret & rev gals 7 1/2% N perf Queen @ acid into tbg	e TAC & estab "C" ne ot to ol excess EFE HC1 4542-45 & set p present pro-	POH w/tbg. lish pmp in rate eat @ end o the btain a 500# cmt out of the acid. RDMO 552 w/2 JSPF okr @ <u>+</u> 4440'.	ate bg. sqz bg. cmt (21 Pmp osed new productive spths. Give blowow	
 MIRU RIH w & pre RIH w Press MIRU Sting press Pull compa MIRU holes RIH w spot 	PU. POH w/rods & /cmt ret, sting ss. cmt company. Sp into ret & so above pmp in p tbg up to 4552 my. POH. WL unit. RIH s). POH. RDMO WL w/trtg pkr, SN acid away. HEE PROFOSED PROGRAM : If to drill or deepen direction any.	& pmp. ND pmp te er & tbg. Set re ot 100 sx C1 "C iz off Delaware ress. Sting out 2' & spot 250 g w/csg guns & unit. & tbg. Rev spot	e. NU BOP. R1s et @ <u>+</u> 4950' & c" & 150 sx C1 perfs. Attemp of ret & rev gals 7 1/2% N perf Queen @ acid into tbg plug back, give data or on subsurface locations	e TAC & estab "C" ne ot to ol excess EFE HC1 4542-45 & set p present pro-	POH w/tbg. lish pmp in rate eat @ end o the btain a 500# cmt out of the acid. RDMO 552 w/2 JSPF okr @ <u>+</u> 4440'.	ate bg. sqz bg. cmt (21 Pmp osed new productive spths. Give blowow	
 MIRU RIH w & pre RIH w Press MIRU Sting press Pull compa MIRU holes RIH w spot 	PU. POH w/rods & /cmt ret, sting ss. cmt company. Sp into ret & so above pmp in p tbg up to 4552 ny. POH. WL unit. RIH s). POH. RDMO WL w/trtg pkr, SN acid away. The PROFOSED PROGRAM : If to drill or deepen direction	& pmp. ND pmp te er & tbg. Set re ot 100 sx C1 "C iz off Delaware ress. Sting out 2' & spot 250 g w/csg guns & unit. & tbg. Rev spot	e. NU BOP. R1s et @ ± 4950' & c" & 150 sx C1 perfs. Attemp of ret & rev gals 7 1/2% N perf Queen @ acid into tbg plug back, give data or on subsurface locations Operations T	e TAC & estab "C" ne ot to ol excess EFE HC1 4542-45 & set p present pro-	POH w/tbg. lish pmp in rate eat @ end o the btain a 500# cmt out of the acid. RDMO 552 w/2 JSPF okr @ <u>+</u> 4440'.	ate bg. sqz bg. cmt (21 Pmp osed new production spths. Give blowow	
 MIRU RIH w & pre RIH w Press MIRU Sting press Pull compa MIRU holes RIH w spot 	PU. POH w/rods & /cmt ret, sting ss. cmt company. Sp into ret & so above pmp in p tbg up to 4552 my. POH. WL unit. RIH s). POH. RDMO WL w/trtg pkr, SN acid away. HEE PROFOSED PROGRAM : If to drill or deepen direction any.	& pmp. ND pmp te er & tbg. Set re ot 100 sx C1 "C iz off Delaware ress. Sting out 2' & spot 250 g w/csg guns & unit. & tbg. Rev spot	e. NU BOP. R1s et @ <u>+</u> 4950' & c" & 150 sx C1 perfs. Attemp of ret & rev gals 7 1/2% N perf Queen @ acid into tbg plug back, give data or on subsurface locations	e TAC & estab "C" ne ot to ol excess EFE HC1 4542-45 & set p present pro-	POH w/tbg. lish pmp in rate eat @ end o the btain a 500# cmt out of the acid. RDMO 552 w/2 JSPF okr @ <u>+</u> 4440'.	ate bg. sqz bg. cmt (21 Pmp osed new productive spths. Give blowod /21/88	

*See Instructions On Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

- MIRU stimulation company. NU surf lines & test to 500#. Place monitor & 6. maintain 500# on csg-tbg annulus. Pmp 1200 gals 7 1/2% NEFE HCl acid. Space out 42 - 7/8" RCNBS through job. Displ acid w/28 bbls 2% KCl wtr. If ballout occurs, surge balls off perfs & continue displ. Rlse pkr & run thru perfs. Pull pkr to ± 4400 ' & set.
- Place, monitor & maintain 500# on csg-tbg annulus. NU surf lines & test 7. to 5000#. Pmp 10,000 gals crosslinked gel w/22,500# sd. RDMO stimulation company.
- 8. Flw back well. When well dies, "lse pkr & POH.
- MIRU WL unit. RIH w/csg guns & perf Queen @ 4006-24' w/2 JSPF (37 9. holes). POH. RDMO WL unit.
- RIH w/RBP w/ball catcher, pkr, SN & tbg. Set RBP @ ± 4100'. Pull pkr ± 10. 10' & set. Test RBP to 1500#. Rlse pkr & pull to ±3900' & set. Swb well dwn to SN.
- MIRU stimulation company. NU surf lines & test to 5000#. Place, monitor 11. & maintain 500# on csg-tbg annulus. Pmp 1800 gals 7 1/2% NEFE HCl acid. Space out 74 - 7/8" RCNBS through job. Displ acid w/25 bbls 2% KCl wtr. If ballout occurs, surge balls off perfs & continue displ. Rise pkr & run thru perfs. Pull pkr to ±3900' & set.
- NU surf lines & test to 5000#. Place, monitor & maintain 500# on 12. csg-tbg annulus. Pmp 16,500 gals crosslinked gel w/38,000# sd. RD stimulation company.
- Flw back well. Rise pkr & rev cut any fill. Rise RBP & POH. 13. 14.
- RIH w/prod tbg. Set TAC, ND BOF. NU pmp tee. RIH w/pmp & rods. Space out pmp & clamp off. Start well pmpg.

NEW MEXICO OIL CONSERVATION COMMISSION WELL LOCATION AND ACREAGE DEDICATION PLAT

A11 dia

		All distances must be	from the outer boundaries of	the Section.	
Operator MER	NDIAN OIL COMPAN	IY	Lease SHINNERY	Well No.	
Unit Letter	Section	Township	Hange	County	
K Actual Footage L	13	18-SOUTH	32-EAST	LEA	
1980	feet from the	SOUTH			
Ground Level Ele		SOUTH line and	1980 fee	t from the WEST	line
3831′		Queen	Wildcat		Dedicated Acreage:
1. Outline	the acreage dedic	ated to the subject w	ell by colored pencil o	r hachure marks on th	Acres
2. If more interest	than one lease is and royalty).	dedicated to the wel	l, outline each and ide	ntify the ownership th	ereof (both as to working
If answe this form No allow	r is "no," list the if necessary.) able will be assign	owners and tract desc	f consolidation	tually been consolida	all owners been consoli- nted. (Use reverse side of nunitization, unitization,
sion.			unit, eliminating suc	h interests, has been	nunitization, unitization, approved by the Commis-
55143	AMOCO 40450	_	MERIDIAN O Inc. 33438	l hereby c tained here	CERTIFICATION artify that the information con- ain is true and complete to the knowledge and belief.
BUDJOY	BUDJOY	MOBIL	MOBIL	Cathy No	kes
56745	56745	0392867	0392867	Position	ns Tech III
	1			Company	
				Meridian	Oil Inc.
	1			Date 10/01/0	
	j		1	10/21/8	<u> </u>
MERIDIA 32410	N OIL INC 32410 	HNG 53239	HNG 53239	shown on the notes of ou under my si	ertify that the well location his plat was platted from field cual surveys made by me or upervision, and that the same d correct to the best of my ond better NELU
MEW	BOURNE OIL		HNG	#	
68817,6	1 100	68817,628		Date Surve	GARY D.
				Registered Pr and/or Land	
	uis.		U.S.	Ceruitoria No	
					6689

NOV 9 1088 CKC) MOBS5 OFFICE

RECENCE