

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 025 30592
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Holloway, F.M.
8. Well No. #1
9. Pool name or Wildcat Knowles Devonian South

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator F&M Oil and Gas Company	
3. Address of Operator P. O. Box 891, Midland, Texas	
4. Well Location Unit Letter <u>J</u> : <u>2086</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>13</u> Township <u>17S</u> Range <u>38E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3682 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP @ 12,000', pump ²⁵ sacks cement (100') on top of CIBP mix 9.5# Gel-Circ Hole w/ mud gel. TOH set 100' plug @ 8500', TOH, set 100' plug @ ⁴⁹¹⁹⁻⁵⁰⁵³ 5000', WOC, tag plug. TOH cut off csg. Set 100' plug, half in and half out of stub. TOH, set 100' plug @ 1000', TOH, set surface plug. Rig down.

Set 100' plug top of salt @ 2327

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Randall Foster TITLE Vice-President DATE 04/11/97
TYPE OR PRINT NAME Randall Foster TELEPHONE NO. (915) 682-7714

(This space for State Use)

Orig. Signed by
Paul Kantz
Geologist

APPROVED BY _____ TITLE _____ DATE APR 17 1997

CONDITIONS OF APPROVAL, IF ANY:

IC

mp
dp