OCD Hobbs

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT** FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No. NM 56749

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals			6. If Indian, Allottee or Tribe Name
	SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well Oil Well Other 2. Name of Operator			8. Well Name and No. Federal USA "L" #3
Concho Oil & Gas Corp.		9. API Well No.	
3. Address and Telephone No. 110 W. LOUISIANA STE 410; MIDLAND, TX 79701 (915) 683-7443		3002530685	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FNL & 1675' FEL, SEC. 14, 19S, 33E.			10. Field and Pool, or Exploratory Area Tonto Seven Rivers
			11. County or Parish, State
			Lea, NM
2.	CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REPORT, C	OR OTHER DATA
	TYPE OF SUBMISSION	TYPE OF ACTION	
	Notice of Intent	Abandonment	Change of Plans
		Recompletion	New Construction
	Subsequent Report	Plugging Back	☐ Non-Routine Fracturing
		Casing Repair	Water Shut-Off
	Final Abandonment Notice	Altering Casing	Conversion to Injection
		Other MIT / Temporarily Abandon Well	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
		ured and true vertical depths for all markders and zones pertinent to this approval to Temporarily Abandon the above well according	•
1. MII 2. RII 3. RII	RU. ND WH & NU BOP. POOH w/ tbg. H w/ CIBP & set @ 3650'. Dump 35' cmt o	pproval to Temporarily Abandon the above well according	to the following procedure:
1. MII 2. RII 3. RII 4. NE	RU. ND WH & NU BOP. POOH w/ tbg. H w/ CIBP & set @ 3650'. Dump 35' cmt of H w/ tbg.to PBTD & load hole w/ 2% KCL DBOP & NU WH w/ BP. RDMO PU.	pproval to Temporarily Abandon the above well according on top. w/ pkr additives. Test csg to 500 psi & record chart. POOl	to the following procedure: H & LD tbg.
1. MII 2. RII 3. RII 4. NE	RU. ND WH & NU BOP. POOH w/ tbg. H w/ CIBP & set @ 3650'. Dump 35' cmt on the following structure and the following structure and the following structure and confect are for Federal or State office use)	pproval to Temporarily Abandon the above well according on top. w/ pkr additives. Test csg to 500 psi & record chart. POOl	to the following procedure: H & LD tbg.
1. MII 2. RII 3. RII 4. NE	RU. ND WH & NU BOP. POOH w/ tbg. H w/ CIBP & set @ 3650'. Dump 35' cmt h w/ tbg to PBTD & load hole w/ 2% KCL D BOP & NU WH w/ BP. RDMO PU. Beby certify that the following is true and correct ace for Federal or State office use) d by ORIG. SGD. JOE G.	pproval to Temporarily Abandon the above well according on top. w/ pkr additives. Test csg to 500 psi & record chart. POOl	to the following procedure: H & LD tbg. Date _05/24/01