UNITED STATES DEP4 MENT OF THE INTERION.M. Oil Co. Division MB No. 1004- 0135 BUREAU OF LAND MANAGEMEN 625 N. French Dr. Expires: November 30, 20

SUNDRY NOTICES AND REPORTS ON TOO BY. NM

	DIVIGI	OI F	MIB No. 1004-0133		
nd	h Dr.	•	res: November 30, 200	00	
8	Lease Seria	l No.	NM-392867	03928	v^{\prime}

S.C.	MURI NOTICES AND P	del Oltis Olt 18	BEEF THE COL	- 1441-03				
	Do not use this form for proposa bandoned well. Use Form 3160-3			If Indian, Allottee, or Tribe	Name			
SUBMIT IN T	APPACASADE (Alica Ansie)			If Unit or CA. Agreement I	Designation			
1. Type of Well Oil Well Gas Well	Other		8.	Well Name and No.				
Name of Operator	Other		IIn.	cle Sam 13 Federal	2			
Devon SFS Operating, Inc.			<u>i—</u>	9. API Well No.				
3a. Address		3b. Phone No. (include	area code)	30-025-	30838			
20 North Broadway, Suite 1500, OKC, C	K 73102	(405)228-7	512	10. Field and Pool, or Exploratory Area				
4. Location of Well (Footage, Sec., T., F	., M., or Survey Description)			Corbin Dela	ware West			
			11.	County or Parish, State				
	13 T-18S R-3	· · · · · · · · · · · · · · · · · · ·			<u>IM</u>			
12. CHECK APPROPI	RIATE BOX(S) TO INDICAT	E NATURE OF NO	TICE, REPORT, OR O	THER DATA				
TYPE OF SUBMISSION		Т	YPE OF ACTION					
X Notice of Intent	Acidize	Deepen	Production (Start/Re	esume) Wa	ter Shut-Off			
2-2-8-1		Fracture Treat	` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` `	Well Integrity				
	Alter Casing		Reclamation	L We	ii integrity			
Subsequent Report	Casing Repair	New Construction	Recomplete	Oth	er			
	Change Plans	Plug and Abandon	Temporarily Aband	on				
Final Abandonment Notice	Convert to Injection Plug Back		Water Disposal	Water Disposal				
Rel TA & POOH w/2 7/8 RU WL. RIH w/5 ½" CII RIH w/4" csg gun & perf RIH w/pkr, SN, & 2 7/8" Spot 3 bbls 15% NEFe ac Acidize zone w/3000 gal Swab test zone. Release pkr & POOH w/tl RIH w/RBP, pkr, & tbg tc PU to 2860'. Spot 2 bbls	s & pump. ND WH & NU "tbg, TA, 6 jts 2 7/8", SN BP to 4920'. Set CIBP & d 7-Rivers 2 SPF (120° phase tbg to 3260'. Pickle tbg w ross perfs. PU to 3110' & s 15% NEFe acid dropping 8 og & pkr. (If non-productive 3100'. Set RBP & test to 15% NEFe across perfs. P 15% NEFe acid dropping 3	& MA. LD 114 jts ump 35' of cmt on ed) from 3208-18', /500 gal pickle acid set pkr. 8 ball sealers evenl ve, set CIBP @ 316 3000 psi. U to 2750' & set pi	top. 3232-38', 3241-46', d. y spaced. SI for 15 r 60') kr.	nin and flow/swab	oack acid load.			
Swab test zone. Evaluate	for additional stimulation.			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	The state of the s			
RIH w/1 jt 2 7/8" tbg, SN, & 2 7/8" J-55 tbg to 3280' (EOT). ND BOP, & NU WH.								
	1½" x 26' RHBC pump, 8		Gr. D rods.					
	on @ 10x100" SPM. RDM	O PU.			9 / 3009			
14. I hereby certify that the foregoing is to Name (Printed/ Typed)	ue and correct.	Title		MINI	2 4 2002			
Karen Cottom /		Fngineering	g Technician	CC				
Signature Wiles Co	Hm	Date	5-16 OZ		BOLANEY Liber Dieen			
75 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 /	THIS SPACE F	OR FEDERAL OR ST	ATE OFFICE USE	College Description				
Approved by		Title						
Conditions of approval, if any are attached certify that the applicant holds legal or equ which would entitle the applicant to conduct the second of the sec	itable title to those rights in the subject	lease	ind willfully to make any depar	tment or agency of the Uni	ed			