m 3160-5 UNITED STATES ne 1990) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT		FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No.
Do not use this form for proposals to d	S AND REPORTS ON WELLS rill or to deepen or reentry to a different reservoir. DR PERMIT—" for such proposals	NM-0392867 6. If Indian, Allottee or Tribe Name
SUBMI	T IN TRIPLICATE	7. If Unit or CA, Agreement Designation
$ \begin{array}{c c} \hline & \text{Type of Well} \\ \hline & \hline & \\ \hline & \hline & \\ \hline & \hline & \\ \hline \\ \hline$		8. Well Name and No.
X Weit Other 2. Name of Operator		Uncle Sam "13" Federal #J
Maralo, Inc.		9. API Well No. 30-025-32055
3. Address and Telephone No. (015) (02. (015) (02. (015))		10. Field and Pool, or Exploratory Area
P. O. Box 832, Midland, 1X 79702 (915) 684-7441 4 Location of Welt (Footage, Sec. T. R. M. or Survey Description)		Corbin, West (Delaware)
1650' FNL & 990' FEL, Sec. 13, T-18-S, R-32-E		11. County or Parish, State
Woit H		
		Lea, NM
12 CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPO	RI, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTIO	
XXX Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Casing Repair	Won-Routine Fracturing
Final Abandonment Notice	Altering Casing	Conversion to Injection
	XX Other Complete in Grayburg	Dispose Water
	"C" Sand.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
1. RUPU. TIH w/2 7/8" tbg, pumping 200 gals 15% NE	all pertinent details, and give pertinent dates, including estimated date of starting bit, & csg scrapers to FC. Circulate hole w/2 FE, double inhibited, to btm of thg then reve	2% KCl wtr. "Pickle" tbg by ersing out.
 PU to 5023'. Spot 200 gals & bit. 	7 1/2% NEFE w/clay stabilizers from 5003' to	o 4803'. TOH /tbg, scrapers,
3. RU perforators using 4" ca holes).	arrier guns, premium charges, and shoot 4 SF	PF from 4995-5003' (total 36
4. TIH w/tbg & pkr to $+/-49$	900'. Reverse spot acid into tbg. Set pkr.	
5. Breakdown perfs by pumpi	ng away spot acid.	
	ping 1000 gals 7 1/2% NEFE w/clay stabilize allout occurs, surge off balls and finish treatment	
7. Swab back load and evalua	ite.	
signed A alter Me	U.1	Date July 29, 1993
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Perturna a seconda da a seconda d	€ (f(, ?)) (f). Date
Title 18 U.S.C. Section 1001, makes it a crime for any perso or representations as to any matter within its jurisdiction.	in knowingly and willfully to make to any department or agency of the Unite	d States any false, fictitious or fraudulent statements

*See Instruction on Reverse Side

- 8. If warranted, RU to frac perfs 4995-5003' w/44,000 gal 30# Spectrafrac + 105,000# 20/40 Ottawa Sand down tbg at a rate of +/- 15 BPM and an anticipated treating pressure of 3,000 psi. Pump as follows:
 - a)
 20,000 gal
 pad

 b)
 6,000 gal + 1-3
 ppg
 20/40 sand

 c)
 6,000 gal + 3-5
 ppg
 20/40 sand

 d)
 6,000 gal + 5-6
 ppg
 20/40 sand

 e)
 6,000 gal + 6
 ppg
 20/40 sand

 f)
 Flush w/slick wtr

Shut in well to allow gel to break.

- 9. Flow/swab back well and evaluate.
- 10. Release pkr. Drop down and tag TD to insure perfs are clear. Clean out sand, if necessary. TOH w/tbg & pkr.
- 11. TIH w/production equipment. Place well on production.