Submit 3 Cories To Appropriate District Office		State of New Mexico		Form C-103 Revised March 25, 1999		
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 87240				WELL API NO		
District II OIL CONSERVATION DIVISION				30-025-324		
811 South First, Artesia, NM 87210  District III  2040 South Pacheco				5. Indicate Typ		
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe NM 87505			STATE	KX FEE		
District IV 2040 South Pacheco, Santa Fe, NM 87505				6. State Oil & VB-03.		
SUNDRY NOTIO	CES AND REPORTS	ON WELL	S	7. Lease Name	or Unit Agreement Nam	e:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					~!!	
PROPOSALS.)	THORTOK I EXMIT	Oldvi C-101/1	OR BOOL	State "	ρ"	
1. Type of Well: Oil Well Gas Well Other						
Oil Well Gas Well Other  2. Name of Operator				8. Well No.		
Xeric Oil & Gas Corporation				#1		
3. Address of Operator PO Box 352 Midland, Texas 79702				9. Pool name o	r Wildcat (San Andres)	
4. Well Location	1exas / 9/02			WIIUCAL	(Dan Andres)	
	550	_				
Unit Letter 0	550 feet from th	ne <u>Sour</u>	th line and	1980 teet fi	rom the <u>East</u> lin	e
Section 2	Township	19S Ra	ange 34E	NMPM Lea	a County	
3561.61.	10. Elevation (Show			)		
	3974 GR	r., di., NI	-turn of Notice E	Pomort or Other	r Data	
	propriate Box to I	indicate in	ature of Notice, R	SEQUENT R		
NOTICE OF INTENTION TO: SUB			_	ALTERING CASING		
	CHANGE PLANS		COMMENCE DRIL		PLUG AND ▼	רסי
					ABANDONMENT *	X
	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	D []		
OTHER:			OTHER:		[	
12 Describe proposed or completed	operations. (Clearly	state all per	tinent details, and gi	ve pertinent dates	, including estimated date	ē
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion						
or recompilation. 1. Set 4-12" CIBP above perforations (5646-58) & cap w/5 sxs.						
2. Circulate hole with plug mud.						
3. Find 4-1/2" casing free pt. & cut @ approx. 3600' & pull out.						
4. Spot 25 sxs across casing stub.						
5. Find 8-5/8" csg free pt. @ approx. 2228', cut & pull out.						
<ul><li>6. Spot 30 sxs across casing stub.</li><li>7. Spot 30 sxs across salt section.</li></ul>						
8. Spot 70 sxs across 13-3/8" csg shoe (100' plug).						
9. Spot 10 sxs at surface.						
10. Cut off well head, i		le marke	r, close work	pit, cutof	f deadman & clear	n
location. //	17 195					
·						
Lhereby certify that the information al	oove is true and comp	olete to the b	est of my knowledge	and belief.		_
	41_				DATE 4/2/01	
SIGNATURE KC Salve	777	TITLE	President	<del></del>	(915)	
Type or print name R. C. Ba	irnett			Tele	phone No. 683-3650	_
	P. Ministra	יו זייויים	(30 m)		DATE	
(This space for State use)  APPPROVED BY  Conditions of approval, if any:	agunson	_111LE	* ***		DAIL	-

5 (2

R

