	UNITED STA	TES	N.M. Oil Cons.		FORM APPROVED	
Form 3160-5 (June 1990)	DEPARTMENT OF TH		1625 N. Frencl		get Bureau No. 1004-0135	
	BUREAU OF LAND MA		Hobbs, NM 88		xpires: March 31, 1993	
			HODDS, MAR OC	D. Lease Desi		
SI	UNDRY NOTICES AND RE	PORTS ON WE	LLS	6 If Indian A	NMLC064790	
Do not use this	form for proposals to drill	l or to deepen o	reentry to a different	reservoir	nottee or Tribe Name	
Use "A	APPLICATION FOR PERMI	T for such prop	posals			
	SUBMIT IN TRIPL			<u> </u>		
1. Type of Well				7. If Unit or C	A, Agreement Designation	
	Gas					
2. Name of Operator				8. Well Name	8 Well Name and No.	
,	perating loc				Mustang Federal #1	
Chi Operating, Inc. 3. Address and Telephone No.				9. API Well No	· ) E - 77 1 8/3	
P.O. Box 1799 Midland, Texas 79702				30	025 - 33289	
4. Location of Well (Footage, T., R., M., or Survey Description)					10. Field and Pool, or Exploratory Area	
467' FSL & 1980' FWL Section 18, T19S, R 33E				Crazy Hors	Crazy Horse Delaware	
407 FSL & 1980 FWL Section 18, 1195, R 33E				11. County or Parish, State		
					Lea	
2. CHECK AF	PPROPRIATE BOX(s) TO I	NDICATE NATU	RE OF NOTICE DEDOR			
TYPE OF	SUBMISSION		TYPE OF ACT	I, UR UTHER		
X Notice of I		X Abandor				
		Recomp		Change of Plan		
Subsequent Report		Plugging			New Construction	
		Casing F			Non-Routine Fracturing	
Final Abandonment Notice		Altering			Water Shut-Off	
		Other	Jashig	Conversion to l	njection	
				Dispose Water (Note: Report rest	ults of multiple completion on Well completion Report and Log form.)	
3. Describe Proposed or (	Completed Operations (Clearly state all	pertinet details, and give	pertinet dates, including estimate	d date of starting an	V proposed work if well is	
Set 13 3/8" @ 50 Set 8 5/8" @ 306 Set 4 1/2" @ 777 RU, pull & LD roc sut & pull 4 1/2" Set 3rd plug @ 3	Completed Operations (Clearly state all ive subsurface locations and measeured 08'. Circ 57 sks cmt. 65'. Circ 100sks cmt. 75'. TOC @ 4400'-CBL. F ds. TOH w/tbg. RU & TIH csg @+4400'. TIH to 50' 8115'-3015' & tag. Set 4th as set out in APD.	Perfd sand string w/WLSCIBP to below csg stub	tor an manders and zones perm <u>+</u> 5950'. TIH & dump ( <u>+</u> 4450') & circ w/brir 58'. Set 5th plug @ su	35' of cmt on ie. Set 2nd p irface - 10 sk	CIBP. Shoot freepo lug @ <u>+</u> 4450'-4350', s.	
Set 13 3/8" @ 50 Set 8 5/8" @ 306 Set 4 1/2" @ 777 RU, pull & LD roc sut & pull 4 1/2" Set 3rd plug @ 3	08'. Circ 57 sks cmt. 65'. Circ 100sks cmt. 75'. TOC @ 4400'-CBL. F ds. TOH w/tbg. RU & TIF csg @+4400'. TIH to 50' 8115'-3015' & tag. Set 4th	Perfd sand string w/WLSCIBP to below csg stub	tor an manders and zones perm <u>+</u> 5950'. TIH & dump ( <u>+</u> 4450') & circ w/brir 58'. Set 5th plug @ su	35' of cmt on ie. Set 2nd p irface - 10 sk	CIBP. Shoot freepo lug @ <u>+</u> 4450'-4350', s.	
Set 13 3/8" @ 50 Set 8 5/8" @ 306 Set 4 1/2" @ 777 RU, pull & LD roc sut & pull 4 1/2" Set 3rd plug @ 3 Reclaim location	08'. Circ 57 sks cmt. 65'. Circ 100sks cmt. 75'. TOC @ 4400'-CBL. F ds. TOH w/tbg. RU & TIF csg @+4400'. TIH to 50' 8115'-3015' & tag. Set 4th as set out in APD.	Perfd sand string w/WLSCIBP to below csg stub	tor an manders and zones perm <u>+</u> 5950'. TIH & dump ( <u>+</u> 4450') & circ w/brir 58'. Set 5th plug @ su	35' of cmt on ie. Set 2nd p irface - 10 sk	CIBP. Shoot freepo	
Set 13 3/8" @ 50 Set 8 5/8" @ 306 Set 4 1/2" @ 777 RU, pull & LD roc Sut & pull 4 1/2" Set 3rd plug @ 3 Reclaim location	08'. Circ 57 sks cmt. 65'. Circ 100sks cmt. 75'. TOC @ 4400'-CBL. F ds. TOH w/tbg. RU & TIF csg @+4400'. TIH to 50' 8115'-3015' & tag. Set 4th	Perfd sand string I w/WLSCIBP to below csg stub n plug @ 558'-4	tor an manders and zones perm <u>+</u> 5950'. TIH & dump ( <u>+</u> 4450') & circ w/brir 58'. Set 5th plug @ su	35' of cmt on ne. Set 2nd p urface - 10 sk	CIBP. Shoot freepo lug @ ±4450'-4350', s.	
Set 13 3/8" @ 50 Set 8 5/8" @ 306 Set 4 1/2" @ 777 RU, pull & LD roc sut & pull 4 1/2" Set 3rd plug @ 3 Reclaim location	08'. Circ 57 sks cmt. 65'. Circ 100sks cmt. 75'. TOC @ 4400'-CBL. F ds. TOH w/tbg. RU & TIH csg @+4400'. TIH to 50' 115'-3015' & tag. Set 4th as set out in APD.	Perfd sand string w/WLSCIBP to below csg stub	tor an manders and zones perm <u>+</u> 5950'. TIH & dump ( <u>+</u> 4450') & circ w/brir 58'. Set 5th plug @ su	35' of cmt on ie. Set 2nd p irface - 10 sk	CIBP. Shoot freepo lug @ <u>+</u> 4450'-4350', s.	
Set 13 3/8" @ 50 Set 8 5/8" @ 306 Set 4 1/2" @ 777 RU, pull & LD roc ut & pull 4 1/2" Set 3rd plug @ 3 Seclaim location	08'. Circ 57 sks cmt. 65'. Circ 100sks cmt. 75'. TOC @ 4400'-CBL. F ds. TOH w/tbg. RU & TIH csg @+4400'. TIH to 50' 115'-3015' & tag. Set 4th as set out in APD.	Perfd sand string I w/WLSCIBP to below csg stub n plug @ 558'-4	tor an manders and zones perm <u>+</u> 5950'. TIH & dump ( <u>+</u> 4450') & circ w/brir 58'. Set 5th plug @ su	35' of cmt on he. Set 2nd p urface - 10 sk	CIBP. Shoot freepo lug @ ±4450'-4350', s.	
Set 13 3/8" @ 50 Set 8 5/8" @ 306 Set 4 1/2" @ 777 RU, pull & LD roc sut & pull 4 1/2" Set 3rd plug @ 3 Reclaim location	08'. Circ 57 sks cmt. 65'. Circ 100sks cmt. 75'. TOC @ 4400'-CBL. F ds. TOH w/tbg. RU & TIH csg @+4400'. TIH to 50' 8115'-3015' & tag. Set 4th as set out in APD.	Perfd sand string I w/WLSCIBP to below csg stub n plug @ 558'-4	gers from 5991-7657'. ±5950'. TIH & dump (±4450') & circ w/brir 58'. Set 5th plug @ si	35' of cmt on ne. Set 2nd p urface - 10 sk	CIBP. Shoot freepo lug @ ±4450'-4350', s.	
Set 13 3/8" @ 50 Set 8 5/8" @ 306 Set 4 1/2" @ 777 RU, pull & LD roc sut & pull 4 1/2" Set 3rd plug @ 3 Seclaim location	08'. Circ 57 sks cmt. 65'. Circ 100sks cmt. 75'. TOC @ 4400'-CBL. F ds. TOH w/tbg. RU & TIH csg @+4400'. TIH to 50' 8115'-3015' & tag. Set 4th as set out in APD.	Perfd sand string I w/WLSCIBP to below csg stub n plug @ 558'-4	gers from 5991-7657'. ±5950'. TIH & dump (±4450') & circ w/brir 58'. Set 5th plug @ si	35' of cmt on he. Set 2nd p urface - 10 sk	CIBP. Shoot freepo lug @ ±4450'-4350' s.	
Set 13 3/8" @ 50 Set 8 5/8" @ 306 Set 4 1/2" @ 777 RU, pull & LD roc out & pull 4 1/2" Set 3rd plug @ 3 Seclaim location	08'. Circ 57 sks cmt. 65'. Circ 100sks cmt. 75'. TOC @ 4400'-CBL. F ds. TOH w/tbg. RU & TIH csg @+4400'. TIH to 50' 8115'-3015' & tag. Set 4th as set out in APD.	Perfd sand string I w/WLSCIBP to below csg stub n plug @ 558'-4	gers from 5991-7657'. ±5950'. TIH & dump (±4450') & circ w/brir 58'. Set 5th plug @ si	35' of cmt on he. Set 2nd p urface - 10 sk	CIBP. Shoot freepo lug @ ±4450'-4350' s.	

\*See Instructions on Reverse Side

Gww

5 C

BUN TTERNE 00. 21. 110

•