

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-34226
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
Hoover SW 32	
8. Well No.	1
9. Pool name or Wildcat	Vacuum; Abo, N.
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
4081' GL	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER Dry Hole

2. Name of Operator
Altura Energy LTD

3. Address of Operator
P.O. Box 4294, Houston, TX 77210-4294

4. Well Location
Unit Letter G : 1650 Feet From The North Line and 1930 Feet From The East Line
Section 32 Township 17-S Range 34-E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Temporary Abandonment ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/12/98 - Decide to TxA well.

1/13/98 - Received plugging instructions from Paul Kautz at the NMOCD, 7:40 a.m. CST.

Spot 45 sx. Cl. 'H' cement plug @ 7618'. Circulate X WOC. Run DP X tag plug @ 7502'. Spot 45 sx. plug @ 6427'; spot 45 sx. plug @ 6212'; spot 45 sx. plug @ 4524'; spot 45 sx. plug @ 2833'; spot 45 sx. plug @ 1648' (all plugs Cl. 'H' cement). Wait 3 hours X tag plug @ 1540'.

1/14/98 - Nipple BOP, nipple up tbghead, and clean pits.

Release rig @ 08:00 hours.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Stephens TITLE Business Analyst (SG) DATE 1/22/98
(281)
TYPE OR PRINT NAME Mark Stephens TELEPHONE NO. 552-1158

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: