District	Submit 3 Copies To Appropriate District Office		New Me		,	Form C-1		
District		Energy, Minerals and Natural Resources			Revised March 25, 1999			
District III 2046 South Pacheco South Pachec	District II	OH CONCEDIATION DIVICION				,		
STATE LEFE					5. Indicate Type	of/Lease		
SUNDRY NOTICES AND REPORTS ON WELLS ON NOT USE THIS FORM FOR PROPOSALS ATO DELIGORY TO DEFFEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-KI) FOR SUCH PROPOSALS) 1. Type of Well/ Oil Well SD Gas Well Other 2. Name of Operator David H. Arrington Oil & Gas, Inc 3. Address of Operator P.O. Box 2071, Midland, Texas 79702 4. Well Location Unit Letter A : 330' feet from the North line and 480' feet from the East line Section 23 Township 17S Range 35E NMPM County Lea 10. Elevation (Show whether DR, RKB, RT, CR, etc.) 3919' GR; 3937' KB; 3936' DF 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMOILA WORK PLUG AND ABANDON SEEMEN UNDER COMPLETION CEMENT JOB OTHER: COMPLETION CHARLE COMPLETION PABANDON PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: COMPLETION CHARLE COMPLETION PABANDON PABANDON PABANDONMENT CEMENT JOB OTHER: COMPLETION PABANDON PABANDON PABANDON PABANDON PABANDONMENT CEMENT JOB OTHER: Complete Drilling 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompliation. 3/20/01- Spudded well at 8:00 a.m. 3/21/01- Drilled 12 ½" hole form 725' to 1800'. 3/23/01- Ran 8 5/8" casing to 1800' and cement with 945 sxs. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50' and WOC. 3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/22/01- Continue drilling 12 ½" hole from 725' to 1800'. 3/22/01- Continue drilling 12 ½" hole from 725' to 1800'. 3/22/01- Continue drilling 12 ½" hole from 725' to 1800'. 3/22/01- Continue drilling 12 ½" hole from 725' to 1800'. 3/22/01- Continue drilling 12 ½" hole from 725' to 1800'. 3/22/01- Continue drilling 12 ½" hole from 725' to 1800'. 3/22/01- Continue drilling 12 ½" hole from 725' to 1800'. 3/22/01- Continue drilling 12 ½" hole f	1000 Rio Brazos Rd., Aztec, NM 87410							
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILLO RO TO DEEPEN OR FLUG BACK TO A DIFFIRMENT RESERVOR. USE "APPLICATION FOR FERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well' 2. Name of Operator 3. Address of Operator 4. Well Location Unit Letter A : 330' feet from the North line and 480' feet from the East line Section 23 Township 178 Range 35E NMPM County Lea 10. Elevation (Show whether DR, RRB, RT, CR, etc.) 3919' GR, 3937' RB, 3936' DF 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CEMENT JOB TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING CIPNS PLUG AND ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING CIPNS PLUG AND ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING CIPNS PLUG AND ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING CIPNS PLUG AND ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING CIPNS PLUG AND ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING CIPNS PLUG AND ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING CIPNS PLUG AND ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING CIPNS PLUG AND ABANDONMENT THERE Complete Drilling 20. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 312001 - Spudded well at 8:00 a.m. 312101 - Drilled 12 ½" hole from 725' to 1800'. 312301 - Ran 8 5/8" casing to 1800' and cement with 945 sxs. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50' and WOC. 312401 - Drilled 17 7/8" hole for 725'. Circ and cement with 945 sxs. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50' and WOC. 312401 - Drilled 1	The state of the s				1	3 Lease No.		
COD NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEBPENOR FLIGID BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PREMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well	SUNDRY NOTICE	S AND REPORTS O	N WELLS	3		r Unit Agreement Nam	ne:	
PROPOSALS Complete Completed Operator Set of Complete Drilling Complete Completed Operator Set of Set o						•		
Oil Well O Gas Well Other	PROPOSALS.)	ONTORTERIMIT (POR	W C-101) FC	K 30CH	Sparkle Dunn "2	23"		
2. Name of Operator David H. Arrington Oil & Gas, Inc 3. Address of Operator 9. Pool name or Wildeat 9. Pool nam		Othon						
David H. Arrington Oil & Gas, Inc 2 9. Pool name or Wildcat P.O. Box 2071, Midland, Texas 79702 9. Pool name or Wildcat Yacuum; Blinebry, NE 4. Well Location Unit Letter A : 330' feet from the North line and 480' feet from the East line Section 23 Township 17S Range 35E NMPM County Lea 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3919' (FR, 3937' (FR, 3936') DF 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON COMPLETION COMPLETION COMPLETION COMPLETION COMPLETION COMPLETION COMPLETION COMPLETION COMPLETION CASING TEST AND ABANDONMENT COMPLETION CO		Other	.		8 Well No			
P.O. Box 2071, Midland, Texas 79702 Vacuum; Blinebry, NE	· -							
Well Location Unit Letter A : 330' feet from the North line and 480' feet from the East line	1							
Unit Letter_A_:_330'fect from the _North line and _480'fect from the _East line Section 23		702			Vacuum; Blinebry, NE			
Section 23 Township 17S Range 35E NMPM County Lea 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3919' GR; 3937' KB; 3936' DF 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Complete Drilling OTHER: Complete Drilling 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 3/20/01- Spudded well at 8:00 a.m. 3/21/01- Drilled 12 ½" hole form 725' to 1800'. 3/23/01- Continue drilling 12 ½" hole from 725' to 1800'. 3/23/01- Ran 8 5/8" casing to 1800' and cement with 945 xss. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50' and WOC. 3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/10/01- Brun DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 xss. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	4. Well Location							
Section 23 Township 17S Range 35E NMPM County Lea 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3919' GR; 3937' KB; 3936' DF 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CASING TEST AND CEMENT JOB OTHER: OTHER: Complete Drilling DIAMADON OTHER: Complete Operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 3/20/01- Spudded well at 8:00 a.m. 3/21/01- Drilled 12 ¼" hole from 725' to 1800'. 3/22/01- Continue drilling 12 ¼" hole from 725' to 1800'. 3/23/01- Ran 8 5/8" casing to 1800' and cement with 945 xss. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50' and WOC. 3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/07/01- Drilled 7 7/8" hole to TD 7750'. 4/8-9/01- Logging. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 xss. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	Unit Letter A : 330'	feet from the N	orth	line and 480'	feet from the	East line		
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3919' GR; 3937' KB; 3936' DF 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON CEMENT JOB PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: Complete Drilling 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 3/20/01- Spudded well at 8:00 a.m. 3/21/01- Drilled 12 ¼" hole form 725' to 1800'. 3/23/01- Ran 8 5/8" casing to 1800' and cement with 945 sxs. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50' and WOC. 3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/07/01- Drilled 77/8" hole to TD 7750'. 4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Engineer DATE 4/26/01 Type or print name Chuck Sledge Telephone No. (915) 682-6685 (This space for State use)		_						
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: Complete Drilling OTHER: OTHER: OTHER: Complete Drilling OTHER: Complete Drilling OTHER:						County Lea		
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Complete Drilling DITEMPTION 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 3/20/01- Spudded well at 8:00 a.m. 3/21/01- Drilled 12 ½" hole 182 m casing to 725'. 3/22/01- Continue drilling 12 ½" hole from 725' to 1800'. 3/23/01- Ran 8 5/8" casing to 1800' and cement with 945 sxs. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50' and WOC. 3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/07/01- Drilled 7 7/8" hole to TD 7750'. 4/8-9/01- Logging. 4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	1	•			<i>c.)</i>			
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: OTHER: Complete Drilling OTHER: Complete Drilling OTHER: Complete Drilling 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 3/20/01- Spudded well at 8:00 a.m. 3/21/01- Drilled 12 ¼" hole from 725' to 1800'. 3/22/01- Continue drilling 12 ½" hole from 725' to 1800'. 3/23/01- Ran 8 5/8" casing to 1800' and cement with 945 sxs. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50' and WOC. 3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/07/01- Drilled 7 7/8" hole to TD 7750'. 4/8-9/01- Logging. 4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	11. Check App				Report or Other	Data		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. ABANDONMENT ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB ABANDONMENT 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 3/20/01- Spudded well at 8:00 a.m. 3/21/01- Drilled 12 ¼" hole form 725' to 1800'. 3/22/01- Continue drilling 12 ¼" hole from 725' to 1800'. 3/22/01- Continue drilling 12 ¼" hole from 725' to 1800'. 3/23/01- Ran 8 5/8" casing to 1800' and cement with 945 sxs. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50' and WOC. 3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/07/01- Drilled 7 7%" hole to TD 7750'. 4/8-9/01- Logging. 4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ¼" casing to 7750'. Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE								
PULL OR ALTER CASING							i 🗆	
OTHER: CASING TEST AND CEMENT JOB	TEMPORARILY ABANDON C	HANGE PLANS		COMMENCE DR	ILLING OPNS. 🗌			
OTHER: OTHER: Complete Drilling 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 3/20/01- Spudded well at 8:00 a.m. 3/21/01- Drilled 12 ¼" hole fam casing to 725'. 3/22/01- Continue drilling 12 ¼" hole from 725' to 1800'. 3/23/01- Ran 8 5/8" casing to 1800' and cement with 945 sxs. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50' and WOC. 3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/07/01- Drilled 7 7/8" hole to TD 7750'. 4/8-9/01- Logging. 4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Engineer DATE 4/26/01 Type or print name Chuck Sledge Telephone No. (915) 682-6685 (This space for State use)				(ND 🗆	ABANDONWENT		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 3/20/01- Spudded well at 8:00 a.m. 3/21/01- Drilled 12 ¼" hole form 725' to 1800'. 3/22/01- Continue drilling 12 ¼" hole from 725' to 1800'. 3/23/01- Ran 8 5/8" casing to 1800' and cement with 945 sxs. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50' and WOC. 3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/07/01- Drilled 7 7/8" hole to TD 7750'. 4/8-9/01- Logging. 4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Engineer DATE 4/26/01 Type or print name Chuck Sledge Telephone No. (915) 682-6685 (This space for State use)	C	OMPLETION		CEMENT JOB				
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 3/20/01- Spudded well at 8:00 a.m. 3/21/01- Drilled 12 ½" hole feet casing to 725". 3/22/01- Continue drilling 12 ½" hole from 725" to 1800". 3/23/01- Ran 8 5/8" casing to 1800" and cement with 945 sxs. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50" and WOC. 3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/07/01- Drilled 7 7/8" hole to TD 7750". 4/8-9/01- Logging. 4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750". Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Engineer DATE 4/26/01 Type or print name Chuck Sledge Telephone No. (915) 682-6685 (This space for State use)	OTHER:			OTHER: Com	olete Drilling		V	
or recompilation. 3/20/01- Spudded well at 8:00 a.m. 3/21/01- Drilled 12 ¼" hole for casing to 725'. 3/22/01- Continue drilling 12 ¼" hole from 725' to 1800'. 3/23/01- Ran 8 5/8" casing to 1800' and cement with 945 sxs. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50' and WOC. 3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/07/01- Drilled 7 7/8" hole to TD 7750'. 4/8-9/01- Logging. 4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	12. Describe proposed or completed of	operations. (Clearly s	tate all per			including estimated da	ate	
3/20/01- Spudded well at 8:00 a.m. 3/21/01- Drilled 12 ¼" hole from 725' to 1800'. 3/22/01- Continue drilling 12 ¼" hole from 725' to 1800'. 3/23/01- Ran 8 5/8" casing to 1800' and cement with 945 sxs. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50' and WOC. 3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/07/01- Drilled 7 7/8" hole to TD 7750'. 4/8-9/01- Logging. 4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	of starting any proposed work). S							
3/21/01- Drilled 12 ¼" hole from casing to 725'. 3/22/01- Continue drilling 12 ¼" hole from 725' to 1800'. 3/23/01- Ran 8 5/8" casing to 1800' and cement with 945 sxs. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50' and WOC. 3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/07/01- Drilled 7 7/8" hole to TD 7750'. 4/8-9/01- Logging. 4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	or recompilation.							
3/21/01- Drilled 12 ¼" hole from casing to 725'. 3/22/01- Continue drilling 12 ¼" hole from 725' to 1800'. 3/23/01- Ran 8 5/8" casing to 1800' and cement with 945 sxs. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50' and WOC. 3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/07/01- Drilled 7 7/8" hole to TD 7750'. 4/8-9/01- Logging. 4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	3/20/01- Spudded well at 8:00 a.m.							
3/23/01- Ran 8 5/8" casing to 1800' and cement with 945 sxs. Wash casing to bottom. Cement and WOC. Ran temp survey TOC at 50' and WOC. 3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/07/01- Drilled 7 7/8" hole to TD 7750'. 4/8-9/01- Logging. 4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	•							
survey TOC at 50' and WOC. 3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/07/01- Drilled 7 7/8" hole to TD 7750'. 4/8-9/01- Logging. 4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE								
3/24/01- WOC, cut off conductor and weld head on. NU BOP's. 3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/07/01- Drilled 7 7/8" hole to TD 7750'. 4/8-9/01- Logging. 4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	3/23/01- Ran 8 5/8" casing to 1800' and cement with 945 sxs. Wash casing to bottom. Cement and WOC. Ran temp							
3/25/01- Test casing to 1000 psi and test BOP's-Ok. 4/07/01- Drilled 7 7/8" hole to TD 7750'. 4/8-9/01- Logging. 4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE								
4/07/01- Drilled 7 7/8" hole to TD 7750'. 4/8-9/01- Logging. 4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE								
4/10/01- Run DST #1 and #2 and LDDP. 4/11/01- Ran 5 ½" casing to 7750'. Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE								
4/11/01- Ran 5 ½" casing to 7750". Circ and cement with 225 sxs. 4/12/01- Clean and jet pits. Released rig at 12:00 p.m. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	4/8-9/01- Logging.							
4/12/01- Clean and jet pits. Released rig at 12:00 p.m. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE								
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	_		ith 225 s	xs.				
SIGNATURE	4/12/01- Clean and jet pits. Release	ed rig at 12:00 p.m.						
SIGNATURE	I hereby certify that the information ab	ove is true and compl	ete to the	pest of my knowled	ge and helief.			
Type or print name Chuck Sledge (This space for State use) APPPROVED BY TITLE Drig. Signed by DAME 1 7001		l la		•	_			
(This space for State use) APPPROVED BY TITLE Drig. Signed by DAME 0 7 2001	SIGNATURE (A.A.	/5//_	_TITLE_	Engineer		_DATE4/26/01	-	
(This space for State use) APPPROVED BY TITLE Drig. Signed by DAME 0 7 2001	Type or print name Chuck Sledge				Telephone N	No. (915) 682-6685		
	A PPPP OVED BV		TITI E	sair signed h) 7	DAME I I SMALL	i	
	* * * * * * * * * * * * * * * * * * *		_111111	Paul Kauts		TAME A LYM	,	