State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT | P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

OIL CONSERVATION DIVISION 310 Old Santa Fe Trail, Room 206 Santa Fe, New Mexico 87503

WELL API NO. 30-025-35447

חופדשורד ווו	M 88210	Courty I C' LACM [A]		30-023-3544/
DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410			5. Indicate Type of Lease	
			STATE Y FEE	
				6. State Oil & Gas Loase No.
SUN	DRY NOT	CES AND REPORTS ON W		26917
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT"			7. Leane Name or Unit Agreement Name	
	(FORM C-1	01) FOR SUCH PROPOSALS.)	'EHMI!"	Zonie Ivame or Umi Agreement Name
I. Type of Well:				
WELL X	MELL			
2. Name of Operator		OTHER		SPARKLE DUNN "23"
DAVID H. ARR	RINGTON C	TI CAG		8. Well No.
Address of Operator	THOTON O	IL & GAS		2
	MIDIAND	m		9. Pool name or Wildcat
. Well Location	O BOX 2071 MIDLAND TEXAS 79702			
	222	-		VACUUM BLINEBRY NE
Unit LetterA	_ : <u>330</u> _	Feet From The NORTH	Jina and //80	
			2166 4100	Feet From The EAST Lin
Section 23	~~~~	Township 17 S	25 E	
		10. Elevation (Show whether	T DF. RKB. RT. GP. etc.)	NMPM LEC County
		3919	- Francisco, City, City,	
•	Check An	monriate Box to Indian	N T	
NOTICE	OF INTE	propriate Box to Indicate NTION TO:	Nature of Notice, Re	port, or Other Data
HOHOL	OF INTE	VIION IO:	SUBS	SEQUENT REPORT OF:
RFORM REMEDIAL WORK		20110 4110 4110 1	1	SEGULINI REPORT OF:
		PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
MPORARILY ABANDON		CHANGE PLANS		_ · · · · · · · · · · · · · · · · · · ·
I OD NEED ALONG			COMMENCE DRILLING	OPNS. L. PLUG AND ABANDONMENT.
LL OR ALTER CASING			CASING TEST AND CEM	
HER:			SHOWING LEST MUDICEW	ENI JOB
			OTHER:	_
	ted Operations	1Classic and 1		
Describe Proposed or Comple				
Describe Proposed or Comple work) SEE RULE 1103.	operation	Citally state all periment details, a	nd give pertinent dates, includ	ing estimated date of storing and managed
Describe Proposed or Complework) SEE RULE 1103.	орелакова	9.5 # MUD	nd give pertinent dates, includ BETWEEN PLUGS	ing estimated date of starting any proposed
SET CIBP @ 7550	O' AND CA	AP WITH 20 SACKS OF	nd give perinent dates, include BETWEEN PLUGS	ing estimated date of starting any proposed
SET CIBP @ 7550 CIRCULATE HOLE	O' AND CA	AP WITH 20 SACKS OF	CEMENT.	ing estimated date of starting any proposed
SET CIBP @ 7550 CIRCULATE HOLE	O' AND CA	AP WITH 20 SACKS OF	CEMENT.	ing estimated date of starting any proposed
SET CIBP @ 7550 CIRCULATE HOLE PUH TO 6700' SE	O' AND CA WITH 9.5	AP WITH 20 SACKS OF MUD.	CEMENT.	ing estimated date of starting any proposed
SET CIBP @ 7550 CIRCULATE HOLE PUH TO 6700' SE PUH TO 4700' SE	O' AND CA WITH 9.5 POT WITH	AP WITH 20 SACKS OF MUD. 25 SACKS PLUG TO 660	CEMENT.	ing estimated date of starting any proposed
SET CIBP @ 7550 CIRCULATE HOLE PUH TO 6700' SE PUH TO 4700' SE CUT CASING AT E	O' AND CA WITH 9.5 POT WITH POT WITH FREE POIN	AP WITH 20 SACKS OF MUD. 25 SACKS PLUG TO 660 25 SACKS PLUG TO 460	CEMENT.	
SET CIBP @ 7550 CIRCULATE HOLE PUH TO 6700' SE PUH TO 4700' SE CUT CASING AT E	O' AND CA WITH 9.5 POT WITH POT WITH FREE POIN	AP WITH 20 SACKS OF MUD. 25 SACKS PLUG TO 660 25 SACKS PLUG TO 460	CEMENT.	
SET CIBP @ 7550 CIRCULATE HOLE PUH TO 6700' SE PUH TO 4700' SE CUT CASING AT E SPOT & 40 SA WOC AND TAG.	O' AND CA WITH 9.5 POT WITH POT WITH FREE POIN ACKS PLUG	AP WITH 20 SACKS OF MUD. 25 SACKS PLUG TO 660 25 SACKS PLUG TO 460 T. (APPROXIMATELY 2 50' INSIDE AND OUT	CEMENT. 00'. 000'. 000'. 000'). 0F 5 1/2 CASING	STUB.
SET CIBP @ 7550 CIRCULATE HOLE PUH TO 6700' SE PUH TO 4700' SE CUT CASING AT E SPOT & 40 SA WOC AND TAG. SPOT WITH 50 SA	O' AND CA WITH 9.5 POT WITH POT WITH FREE POIN ACKS PLUG	AP WITH 20 SACKS OF MUD. 25 SACKS PLUG TO 660 25 SACKS PLUG TO 460 T. (APPROXIMATELY 2 50' INSIDE AND OUT	CEMENT. 00'. 00'. 000'. 0F 5 1/2 CASING	STUB.
SET CIBP @ 7550 CIRCULATE HOLE PUH TO 6700' SE PUH TO 4700' SE CUT CASING AT E SPOT A 40 SA WOC AND TAG. SPOT WITH 50 SA PUH TO 520 AND	O' AND CA WITH 9.5 POT WITH POT WITH FREE POIN ACKS PLUG	AP WITH 20 SACKS OF MUD. 25 SACKS PLUG TO 660 25 SACKS PLUG TO 460 T. (APPROXIMATELY 2 50' INSIDE AND OUT ACROSS 8 5/8 SHOE @	CEMENT. 00'. 00'. 000'. 0F 5 1/2 CASING	STUB.
SET CIBP @ 7550 CIRCULATE HOLE PUH TO 6700' SE PUH TO 4700' SE CUT CASING AT E SPOT A 40 SA WOC AND TAG. SPOT WITH 50 SA PUH TO 520 AND	O' AND CA WITH 9.5 POT WITH POT WITH FREE POIN ACKS PLUG	AP WITH 20 SACKS OF MUD. 25 SACKS PLUG TO 660 25 SACKS PLUG TO 460 T. (APPROXIMATELY 2 50' INSIDE AND OUT ACROSS 8 5/8 SHOE @	CEMENT. 00'. 00'. 000'. 0F 5 1/2 CASING	STUB.
SET CIBP @ 7550 CIRCULATE HOLE PUH TO 6700' SE PUH TO 4700' SE CUT CASING AT E SPOT A 40 SA WOC AND TAG. SPOT WITH 50 SA PUH TO 520 AND	O' AND CA WITH 9.5 POT WITH POT WITH FREE POIN ACKS PLUG	AP WITH 20 SACKS OF MUD. 25 SACKS PLUG TO 660 25 SACKS PLUG TO 460 T. (APPROXIMATELY 2 50' INSIDE AND OUT	CEMENT. 00'. 00'. 000'. 0F 5 1/2 CASING	STUB.
SET CIBP @ 7550 CIRCULATE HOLE PUH TO 6700' SE PUH TO 4700' SE CUT CASING AT E SPOT A 40 SA WOC AND TAG. SPOT WITH 50 SA PUH TO 520 AND	O' AND CA WITH 9.5 POT WITH POT WITH FREE POIN ACKS PLUG	AP WITH 20 SACKS OF MUD. 25 SACKS PLUG TO 660 25 SACKS PLUG TO 460 T. (APPROXIMATELY 2 50' INSIDE AND OUT ACROSS 8 5/8 SHOE @	CEMENT. 00'. 00'. 000'. 0F 5 1/2 CASING	STUB.
SET CIBP @ 7550 CIRCULATE HOLE PUH TO 6700' SE PUH TO 4700' SE CUT CASING AT E SPOT A 40 SA WOC AND TAG. SPOT WITH 50 SA PUH TO 520 AND 10 SACKS SURFA	O' AND CA WITH 9.5 POT WITH POT WITH FREE POIN ACKS PLUG ACKS PLUG SPOT 40 CE PLUG	AP WITH 20 SACKS OF MUD. 25 SACKS PLUG TO 660 25 SACKS PLUG TO 460 T. (APPROXIMATELY 2 50' INSIDE AND OUT ACROSS 8 5/8 SHOE @	CEMENT. OO'. OO'. OOO'). OF 5 1/2 CASING 1800' WOC AND T	STUB.

rank K. Ime AGENT 04-25-01 TYPE OR PROFT NAME IJ MES (This space for State Use) Orig. Signed by Paul Koutz Geologist MAY Q 1 2001 MONGOP ATTROVAL, IP ANY:

ユー

