

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Olsen Energy, Inc.

3. Address and Telephone No.

16414 San Pedro, Suite 470, San Antonio, Texas 78232 (210)496-2466

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FSL & 330' FWL - Unit M

S35, 20, 34

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.

LC-029519A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

B.V. Lynch "A" Fed No. 6

9. API Well No.

30-025-02508

10. Field and Pool, or Exploratory Area

Lynch/Yates-SR

11. County or Parish, State

Lea

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well Conditions: 5 1/2" 15.5# casing set @ 3666' cemented to surface. Completed open hole 3666'-3726'.

Proposed Plugging Procedure:

1. Set cast iron bridge plug at 3600' w/ 20' cement on plug. *35' if by trailer*
2. Spot 15 sack plug at 1570'-1670'. *50' if by tbg.*
3. Spot 15 sack plug at 0-100'.
4. Cut off casing 3' below ground and install abandonment marker.

14. I hereby certify that the foregoing is true and correct

Signed *Dick Mott*

Title Drilling & Production Manager

Date 12-15-94

(This space for Federal or State office use)

Approved by *Eng. Signed by Shannon J. Shaw*
Conditions of approval, if any:

Title **PETROLEUM ENGINEER**

Date 1/9/95