UNITED STATES SUBMIT IN TRIBUGATES  DEPARTME ( OF THE INTERIOR PARTS SUBMIT IN TRIBUGATES DEPARTMENT OF THE INTERIOR PARTS SUBMIT IN TRIBUGATES DEPARTS SUBMIT IN TRIBUGATES DEPARTS SUBMIT IN TRIBUGATES DEPARTMENT OF THE INTERIOR PARTS SUBMIT SUBMIT SUBMIT SUBMIT S	Form approach Budget But 5. LEASE DESIGNATION LC 06088	reau No. 42-R1424. ON AND SERIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS 300.10 (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTT	EE OR TRIBE NAME
1.	7. UNIT AGREEMENT	NAME
WELL GAS WELL OTHER	South Pearl Queen	
2. NAME OF OPERATOR	8. FARM OR LEASE N	AME
Tamarack Petroleum Co., Inc.		
3. ADDRESS OF OPERATOR 500 W. Texas, Suite 1485, Midland, TX 79701	9. WELL NO.	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.	10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface	Pearl Queen	
1650' FSL and 990 FWL, Section 4, T-20-S, R-35E		
	4-20S-3	5E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARIS	SH 13. STATE
3686 DR	Lea	NM
16. Check Appropriate Box To Indicate Nature of Notice, Report, or O		
SUBSEQUE	SEQUENT REPORT OF:	
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING	WELL
FRACTURE TREAT  MULTIPLE COMPLETE  FRACTURE TREATMENT	ALTERING	<del>-</del>
SHOOT OR ACIDIZE  ABANDON*  SHOOTING OR ACIDIZING  REPAIR WELL  CHANGE PLANS  (Other)	ABANDONM	ENT* X
(Other)  (Other)  (Other)  (Other)  (Other)  (Other)  (Other)	of multiple completion	n on Well
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, if proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical nent to this work.)  1. Move in and rig up plugging unit on 4/16/86. Pick up and reopen ended tubing. Tag up at 4700'. Circulated to 4909'.	depths for all marke	ers and zones perti-
<ol> <li>Spot 50 sks cement at 4909'. Pull out of hole.</li> <li>4/17/86 Plug at 4161'. Circulated hole with 10# mud. Spot 2 Pull out of hole.</li> <li>Rig up to pull casing. Shot 5 1/2" casing at 1871'. Laid do 5. Run in hole with 2 3/8" tubing and spot 65 sks cement at 196. 4/18/86 Run in hole with 2 3/8" tubing and spot 65 sks cement at 90'.</li> </ol>	own 56 jts. 5 920'. Pull ou	1/2" casing. t of hole.
7. Pump 10 sks cement at 60' to surface.		
8. Set dry hole marker and clean location.	-	
		•
18. I hereby certify that the . Factor is true and correct		-
SIGNED	_ DATE5/	8/86
(This space for Federal or State on the state of the stat		7

TITLE

DATE 16-286