

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

JUL 23 10 01 AM '69

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.

13788

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator PAN AMERICAN PETROLEUM CORPORATION	8. Farm or Lease Name STATE "B"
3. Address of Operator BOX 68, HOBBS, N. M. 88240	9. Well No. 2
4. Location of Well UNIT LETTER <u>A</u> , <u>990</u> FEET FROM THE <u>NORTH</u> LINE AND <u>330</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>1</u> TOWNSHIP <u>19-S</u> RANGE <u>36-E</u> NNPM.	10. Field and Pool, or Wildcat EUMONT-OIL
15. Elevation (Show whether DF, RT, GR, etc.) 3747' RDB	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Eumont Zone depleted - Workover possibilities have been exhausted.

Propose to P & A as follows:

Spot 25 Sx Cement plug: - Across perp 3992-4047'  
- Cut & Pull 5 1/2" from approx 2300'  
- 5 1/2" out of 5 1/2" casing slot  
- @ 1602' - (T-Salt)  
- In & out 8 7/8" Csg @ 320'  
Spot 10 at @ Surface and Erect P & A marker.  
Make Final Cleanup & restore ground to contour

TD - 4050'  
PBD - 4048  
5 1/2" CSA 4050 w/ 700 Sx  
8 7/8" CSA 320' - Circ.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	TITLE AREA SUPERINTENDENT	DATE JUL 25 1969
APPROVED BY <u>John W. Runyon</u>	TITLE Geologist	DATE JUL 23 1969
CONDITIONS OF APPROVAL, IF ANY: 1-NSW 1-SUS 1-RP4		