

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>Gulf Oil Corporation</b>		8. Farm or Lease Name <b>C. T. Bates</b>
3. Address of Operator <b>Box 670, Hobbs, N.M. 88240</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>P</b> <b>660</b> FEET FROM THE <b>south</b> LINE AND <b>660</b> FEET FROM THE <b>east</b> LINE, SECTION <b>26</b> TOWNSHIP <b>19S</b> RANGE <b>36E</b> NMPM.		10. Field and Pool, or Wildcat <b>Monument</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3648' GL</b>		12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <b>Plug back and acidize.</b> <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**3973' TD.**

**Pull tubing, clean out hole if necessary, plug back with Hydramite to approximately 3950'.  
Acidize with 3,000 gallons; swab and test and return well to production.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY  
**C. D. BORLAND**

SIGNED \_\_\_\_\_

TITLE **Area Production Manager**

DATE **4-19-71**

APPROVED BY \_\_\_\_\_

TITLE **SUPERVISOR DISTRICT 1**

DATE **APR 21 1971**

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 2 1971

OIL CONSERVATION COMM.  
HOBBS, N. M.