

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-154	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation		8. Farm or Lease Name State "D"
3. Address of Operator Drawer "D", Monument, New Mexico 88265		9. Well No. 1
4. Location of Well UNIT LETTER <u>D</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>1</u> TOWNSHIP <u>20-S</u> RANGE <u>36-E</u> NMPM.		10. Field and Pool, or WHdeat Eunice-Monument G-SA
15. Elevation (Show whether DF, RT, GR, etc.) 3608' DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Plan to: Pull rods, pump and tbq., plug back Grayburg San Andres zone in OH f/3880' to 3865' w/cement. WOC and acidize G/SA zone in OH f/3760 to 3865' w/1000 gal. 15% NE HCl acid and swab test. Set retrievable bridge plug in 7" csg. @ 3750' and perf. 7" csg. opposite G/SA zone f/3688 to 3698', 3712 to 3721', 3726 to 3729', 3731 to 3734' and f/3737 to 3744' w/2 SPF. Acidize w/2000 gal. 15% NE HCl acid and swab test. Recover bridge plug, re-run tbq., pump and rods and resume production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Clerk DATE 8-6-84

ORIGINAL SIGNED BY [Signature]
DISTRICT SUPERVISOR

APPROVED BY [Signature] TITLE DATE AUG 10 1984

CONDITIONS OF APPROVAL, IF ANY: