

UNITED STATES OF AMERICA
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <u>Injection Well</u>	5. LEASE DESIGNATION AND SERIAL NO. <u>LC-031622B</u>
2. NAME OF OPERATOR <u>Conoco Inc.</u>	6. IF INDIAN, A LOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>660' FNL & 660' FEL - Unit Letter A</u>	8. FARM OR LEASE NAME <u>Reed Sanderson</u>
14. PERMIT NO. <u>30-025-04190</u>	9. WELL NO. <u>1</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	10. FIELD AND POOL, OR WILDCAT <u>Dumont 1st & 2nd Rms. Que.</u>
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data	11. SEC., T., R., & OR BLK. AND SURVEY OF AREA <u>4-20S-36E</u>
	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRR. RTH w/ workstring open ended. Tag Baker. Model D-4 cement retainer at 3700' & pull up 2'.
2. Pump 25 sacks class "C" neat cement. Displace w/ 20 bbls 10 ppq mud. POOH btm of Hg at 4450'. Pump 120 bbls 10 ppq mud.
3. POOH until btm of Hg is at 4125'. Pump 45 sacks cement until it cures. POOH
4. Cutoff csq. Fill w/ cement gum plug to surface if necessary. Install P&A marker

RECEIVED
MAY 11 1989

18. I hereby certify that the foregoing is true and correct

SIGNED William W. Baker
William W. Baker

TITLE Administrative Supervisor

DATE May 3, 1989

(This space for Federal or State office use)

APPROVED BY [Signature]
CONDITIONS OF APPROVAL, IF ANY:

FOR: [Signature]
TITLE

DATE 5-22-89

Subscribed to
This Approval
by State

*See Instructions on Reverse Side