. C COPIES RECEIVED	7		
TRIBUTION			Form C-103 Supersedes Old
NT A FE	NEW MEXICO OIL CONSERVATION COMMISSION		C-102 and C-103
FILE	The mexico of each	MSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.	7		5a. Indicate Type of Lease
LAND OFFICE	7		State. Fee X
OPERATOR		•	5. State Oil & Gas Lease No.
<u> </u>	_		0. 5.5.5 S. G GGD E5635 NO.
SUND	RY NOTICES AND DEPORTS C	NI WELLS	mmmmmmm
(DO NOT USE THIS FORM FOR PR USE "APPLICA	OPPOSALS TO DRILL OR TO DEEPEN OR PLUITION FOR PERMIT - " (FORM C-101) FOR	IN WELLS G BACK TO A DIFFERENT RESERVOIR.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. 1.			7. Unit Agreement Name
OIL X GAS WELL	OTHER-		7. Out Agreement Indine
2. Name of Operator			8. Farm or Lease Name
Atlantic Richfield Company			
3. Address of Operator			Mary J. Byrd 9. Well No.
P. O. Box 1710, Hobbs, New Mexico 88240			_
4. Location of Well			10. Field and Pool, or Wildcat
INSTANTAGE G	2310 Nort	h 1650	
UNIT LETTER G ; 2310 FEET FROM THE NOTTH LINE AND 1650 FEET FROM			Monument
THE East LINE, SECTION 11 TOWNSHIP 20S RANGE 36E NMPM.			
LINE, SECT	TOWNSHIP	RANGE JOE NMP	~. (
	15, Elevation (Show whether	er DF, RT, GR, etc.)	12. County
	3577' (
16. Chark			Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF I	NIENTION TO:	SUBSEQUE	NT REPORT OF:
PERFORM REMEDIAL WORK	. l v	7	<u> </u>
	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	_	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
OTHER	_	OTHER	
		١/	
17. Describe Proposed or Completed O	perations (Clearly state all pertinent de	etails, and give pertinent dates, includi	ng estimated date of starting any proposed
work) SEE RULE 1103.		,	any proposed
Set retainer @ 3700' &	squeeze open hole w/100	sx Class H cmt. Load	11
& recover 7" csg @ free	noint. Snot 40 sy cmt	nlug in 7" ogg stub	noie w/9# mud. Cut off
& recover 7" csg @ free point. Spot 40 sx cmt plug in 7" csg stub. Set 9-5/8" cmt retainer on tbg @ 1430' & cmt w/100 sx. Cut off & recover 9-5/8" csg @ free point. Spot 50 sx cmt			
plug in 9-5/8" csg stub & 50 sx cmt plug across 12%" csg shoe. Spot 10 sx cmt plug top well			
& erect dry hole marker	Work to start $11/1/7$	ss 123 csg snoe. Spot	10 sx cmt plug top well
	. Work to Start 11/1/1/	4.	
	•	•	
•	,		
		•	
		7944. 3275343.0	SCIDAL MAST BE MOTIFIED OF
		- 1146 교 (1146) - 네가 크게 가능	SSIDM MUST BE NOTIFIED 24 DR TO THE DEGINNING OF
		File of State of the	PREMATIONS FOR THE C-103
		TO BL APPR	OVED -
		1.55 195 24.14	
•			
18. I hereby certify that the information	above is true and complete to the back	of my knowledge and ball f	
1/2 77	to the best	or my knowledge and Dellel.	
	0		
SIGNED HE LENS	TITLE	Dist. Drlg. Supv.	
77 7	A. C. 15-		
,	Orig. Signed by		
APPROVED BY	Joe D. Ramey		DATE
CONDITIONS OF APPROVAL, IF ANY	Dist. I, Supv.		-

CONDITIONS OF APPROVAL, IF ANY: