

Eunice Monument South Unit #106  
Lea County, New Mexico

Summarized Workover Procedure:

This workover was designed to replace an existing pump with a larger pump in order to produce more fluid. Ultimately, the excess water will be pumped off and an increase in oil production will occur.

1. MIRU pulling unit.
2. POH with rods and pump.
3. RIH with new pump and rods.
4. Space out and clamp off.
5. Hang well on. RD pulling unit.
6. Test pump and put back on production.
7. Notify field office personnel of well status.