Form 3160-5 (November 1983) (-2 ⁷ :neriy 9-331)	U [▲] 'TED STATES DEPARTN 「OF THE INTE				CATE	Budget Bureaus No. 1004-0135 Expires August 31, 1985		
(c areny 3-301)	BUREAU OF LAND MAI			verse stel			5. LEASE DESIGNATION AND SETIAL NO. NM-02053 - 8910086960	
(Do not use th	NDRY NO	TICES AND	REPORTS	ON WEELS ack to a different reervoir. pposal		& FINDIAN, ALLOTTEE OR		
				C S NS		7. UNIT AGREEMENT NAME		
OL GAS WELL VIEL	OTHER		(N+ En		EAST EUMONT	JNIT	
2 NAME OF OPERATOR OXY USA INC.						8. FARM OR LEASE NAME		
3 ADDRESS OF OPERATOR	P.O. BOX 5	0250 MIDLAN	D, TX 79710	×0		9.WELLNO. 13		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*						10. FIELD AND POOL, OR WI	LDCAT	
See also space 17 below.) At surface						EUMONT YATES 7 RVR QN		
660 FNL 1652 EWE NWNE						11. SEC. T., R., M., OR BLK AND SURVEY OR AREA		
14. PERMIT NO.		15. ELEVATIONS (SH	iowwheter DF, RT, GR			SEC 4 T19S	R37E	
300250555600)S01			3691		LEA	NM	
16.	Check Appr	poriate Box To	Indicate Nat	ure of Notices, Repo	rt or			
	CE OF INTENTION 1		1			QUENT REPORT OF:		
TESTWATER SHUT-OF FRACTURE TREAT SHOOT OR ACIDIZE	MU MU	LLORALTER CASING LTIPLE COMPLETE WIDON*		WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACID/2005		HEPAIRING (ALTERING C ABANDONM	ASING	
REPARWELL		ANGE PLANS		(Olher)				
(Other) BE-ACTI		ICER	x	(Note: Report r Completion or tinent details, and five pertin	Recomp	f multiple completion on V letion Report and Log for	- \	
nent to this work.)*		D - 3960'	PBTD - 3958	3' PERFS - 388	4' - 39	DEC 54'	7 1993	
SEE OTHER SIDE						Dec 10 11 10 MI '93	A HO HIVED	
18. Thereby certify that the for SIGNED		IOE G. LARA	111LE 	ULATORY ANALYST	IGIN	DATE ER/4//	3	
CONDITIONS OF A	PPROVAL, IF A		Instructions of	on Reverse Side				

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fradulent statements or representations as to any matter within its jurisdiction.

- 1.) MIRU pulling unit. ND WH, NU BOP.
- 2.) TIH w/ 3 3/4" RB and DC's on 2 7/8" tubing and tag cmt. Drill out cmt from surface to bottom of cmt at approximately 2153' (Note: 3 5/8" RB set down @ 2200' in 1983'). CO wellbore to PBTD of 3958' if necessary. TOOH w/ RB, DC's and tbg.
- 3.) RU wireline. Run GR/N/CCL log from PBTD to minimum depth. Perforate Penrose formation (3790' - 3882') w/ premium charges 2 JSPF at the following depths (3790' - 3811', 3816' - 24', 3829' - 34', 3844' - 50', 3858' - 62', 3875' - 3882'). Total of 114 shots. Depth reference log Lane Wells Radioactivity log dated August 17, 1956.
- 4.) TIH w/ treating pkr on 2 7/8" tbg and set pkr ℓ ± 3690'. Pressure test csg to 500#.
- 5.) RU acid company, pressure backside to 500#, Acidize Penrose perfs (3790' - 3954') w/ 5000 gals 15% NE Fe HCl containing 2% AS-66 and utilizing benzoic acid flakes and rock salt as block. Flush w/ 2% KCl water containing 1% AS-66.
- 6.) Swab test.
- 7.) TOOH w/ pkr and tbg. TIH w/ 2 7/8" tbg. ND BOP, NU WH. TIH w/ rods and pump, RD MO pulling unit.