

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fed ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☒ OTHER- Dual		7. Unit Agreement Name
2. Name of Operator GULF OIL CORPORATION		8. Farm or Lease Name C. H. Kyte
3. Address of Operator P. O. Box 670, Hobbs, NM 88240		9. Well No. 1
4. Location of Well UNIT LETTER P 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 19S RANGE 37E N.M.P.M.		10. Field and Pool, or Wildcat Eunice Monument Eumont Gas
15. Elevation (Show whether DF, RT, GR, etc.) 3700' GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOBS ☐	
OTHER Abandon Eumont perfs & produce Eunice Monument as single ☒		OTHER ☐	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Kill well if necessary w/8.6# GKF. POH w/rods & pump; POH w/2-3/8" tbg. Fsh 2-3/8" & Baker lok-set pkr. Fsh 2-3/8" tbg & cut out Baker "D" pkr. Set RBP @ 3700'. Tst RBP & tbg to 3000#. Cap RBP w/10' frac sd. Sq Eumont perfs 3500'-3634' (220 holes) w/150 sx C1 "C" cmt + low wtr loss additives (125cc wtr loss and 4 1/2 hr pump time @ 125° F). Sq using Gulf's Hesitation Sq Method. Drl up cmt plug to 3650', pres tst sq to 500#. Resq if necessary. Drl up rest of cmt. Clean out to RBP @ 3700'. Rcvr RBP. GIH to ck for fill or junk. Clean out to 3980'. GIH w/2-3/8" tbg. ND BOP, NU WH, run pump and rods. Hang well on. If necessary do a 1000 gal dump acid job.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. B. Sekes, Jr. TITLE Area Engineer DATE 5-15-80

APPROVED BY John Runyan TITLE Geologist DATE MAY 16 1980

CONDITIONS OF APPROVAL, IF ANY: