

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**OIL CONSERVATION DIVISION**

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05628
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-6506-1
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 2
8. Well No.	5
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Amerada Hess Corporation
3. Address of Operator P.O. Box 840, Seminole, Texas 79360	4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>18</u> Township <u>19S</u> Range <u>37E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: CONVERT TO INJECTION WELL. ☒

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #205

Order No. R-9596

Plan to:

MIRU PU. MIRU REVERSE UNIT. TOH W/RODS (LAYING DWN.). CIRC. KILL FLUIDS AS REQUIRED.  
INSTALL BOPS. TOH W/2-7/8" TBG. TIH W/RBP ON TBG. SET RBP @ +/-3.750'. TST. CSG. TO 700  
PSIG. PU & TIH W/4-5/8" SHOE W/KUTRITE ON LIP ONLY & WASH PIPE. D.C.'S. & TBG. TAG PBD @  
4.003' (LYNES OH PKR.). DRILL OUT PKR. CLEAN OUT TO TD-4.039'. TOH. DRILL 20' NEW HOLE TO  
4.059'. TOH W/TBG. MIRU LOGGERS. TIH W/3-1/8" GRN/CCL LOG FR. 4.059'-3.250'. RDMO LOGGERS.  
TIH W/2-7/8" TBG. & SONIC HAMMER TOOL. WASH TO TD (4.059') PUMPING 5-6 BPM IN CIRC. MODE.  
MIRU ACID COMPANY. ACIDIZE FR. 3.836'-4.059' W/11.200 GALS. 15% HCL ACID THRU SONIC HAMMER.  
SHEAR DRAIN PLUG ON SONIC HAMMER. SWAB LOAD TO TANK. TOH W/TBG. (LAYING DWN.). PU & TIH  
W/INJ. TBG. & 5-1/2" PKR. SET PKR. AT +/-3.775'. ND BOPS. FLANGE UP 7-1/16" 3M X 2-1/16"  
(CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE \_\_\_\_\_ DATE 05-23-97  
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY CHRIS WILLIAMS  
DISTRICT I SUPERVISOR TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: