

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240DISTRICT II
P.O. Drawer DD, Artesia, NM 88210DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05653
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-2052-3
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 5
8. Well No.	13
9. Pool name or Wildcat	EUNICE MONUMENT G/SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS

WELL ☐

OTHER

2. Name of Operator

AMERADA HESS CORPORATION

3. Address of Operator

POST OFFICE DRAWER D, MONUMENT, NEW MEXICO 88265

4. Well Location

Unit Letter M : 660 Feet From The SOUTH Line and 660 Feet From The WEST Line

Section

19

Township

19S

Range

37E

NMPM

LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:PERFORM REMEDIAL WORK ☒PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐CHANGE PLANS ☐PULL OR ALTER CASING ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐CASING TEST AND CEMENT JOB ☐OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Move in and rig up pulling unit and reverse unit. TOH with rods and pump. ND wellhead. NU BOP. TOH with tubing. RU Schlumberger and perforate with 3 3/8" casing gun from 3,832'-3,856' and 3,860'-3,874' with 2 SPF 180 deg. phased (38 feet, 78 holes total). RD Schlumberger. RU acid co. Trip in hole with Sonic Hammer on tubing. Acidize well with 5,000 gals. 15% NEFE DI HCL w/3% DP-77MX Micellar solvent. Move tool across perfs and openhole from 3,832'-3,932' throughout acid job. RD acid company. Trip out of hole with Sonic Hammer. Trip in hole with tubing and packer. Set packer at ±3,750'. Swab back load. Trip out of hole with tubing and packer. Trip in hole with prod. tubing. Nipple down BOP. Trip in hole with rods and pump. Nipple up wellhead. Rig down and move out pulling unit. Clean and clear location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE Sr. Staff Assistant DATE 04-25-95TYPE OR PRINT NAME Terry L. Harvey TELEPHONE NO. 393-2144

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISORAPPROVED BY _____ TITLE _____ DATE MAY 01 1995

CONDITIONS OF APPROVAL, IF ANY:

NOT
1672d

RECEIVED
APR 2 1965
U.S. AIR FORCE
OFFICE