

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05740
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1533
7. Lease Name or Unit Agreement Name NORTH MONUMENT G/SA UNIT BLK. 10	
8. Well No.	7
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P. O. Box 840, Seminole, Texas 79360	
4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line Section <u>30</u> Township <u>19S</u> Range <u>37E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: CONVERT TO INJECTION WELL. ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1007

Permit No. WFX716

MIRU PU & RU. TOH W/PROD. EQUIP. & TBG. SET RBP @ +\ -3,675'. CIRC. HOLE W/WATER & TST. CSG. TO 500 PSI. CHG. OUT WELLHEAD. REMOVE RBP. DRILL-OUT O.H. TO 3,964' W/5-7/8" BIT (DUE TO TIGHT SPOT AT 3,775'). CIRC. HOLE CLEAN. RUN GRN/BHC FR. 3,964'-3,200'. SHUT SONIC LOG OFF @ 3,842'. TIH W/SONIC HAMMER TO TD. WASH TO 3,721'. ACIDIZE FR. 3,721'-3,964' W/12,200 GALS. HCL USING SONIC HAMMER. SWAB BACK LOAD. EVALUATE FOR SAN ANDRES COMMUNICATION. IF COMMUNICATION EXISTS, PLUG BACK W/CMT. TIH W/INJ. EQUIP. SET PKR. @ +\ -3,675'. RDMO. SI. OBTAIN 72 HOUR SBHP DIP-IN.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ferry L. Harvey TITLE SR. STAFF ASSISTANT DATE 7-17-97
TYPE OR PRINT NAME FERRY L. HARVEY TELEPHONE NO. 915 758-6700

(This space for State Use)

APPROVED BY Cherie Kerri TITLE OIL & GAS INSPECTOR DATE 8-4-97
CONDITIONS OF APPROVAL, IF ANY: