

50-1-11

AMERADA HESS CORPORATION

P. O. DRAWER "D"
MONUMENT, NEW MEXICO 88265

Workover Procedure State O #4

- 1) Establish injection rate down surface casing.
- 2) Perform tracer survey down surface casing to verify fluid movement below surface casing setting depth at 175'.
- 3) Perform bradenhead squeeze on surface casing using 100 sks. Class C neat cement.
- 4) CI for 24 hours and monitor surface casing for pressure communication.

RECEIVED
JUL 16 1986
O.C.S.
HOBBS OFFICE