

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

WELL API NO.	30-025-05749
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B-1481-15
7. Lease Name or Unit Agreement Name	
NORTH MONUMENT G/SA UNIT BLK. 10	
8. Well No.	11
9. Pool Name or Wildcat	
EUNICE MONUMENT G/SA	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
AMERADA HESS CORPORATION

3. Address of Operator
POST OFFICE DRAWER D, MONUMENT, NEW MEXICO 88265

4. Well Location
Unit Letter K : 1980 Feet From The SOUTH Line and 1980 Feet From The WEST Line

Section 30 Township 19S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Move in and rig up pulling unit. Nipple down head. Trip out of hole with rods. Nipple up BOP. Trip out of hole with tubing. Trip in hole with bit, drill collars and tubing. Clean out openhole to TD. Trip out of hole with bit. Rig up cementers. TIH with tbg. open ended and spot cement plug from 3,970'-3,924'. (Use oyster shells to establish circulation if necessary). WOC 24 hours. Rig up acid co. TIH with sonic hammer on tubing to TD. Acidize openhole with 5,000 gals. 15% NEFE DI HCL w/3% DP-77MX. RD acid co. TOH with tubing and tool. TIH with packer and set at ±3,700'. Swab back load. TOH with packer and tubing. Trip in hole with production tubing. Nipple down BOP. Nipple up wellhead. Trip in hole with rods and pump. Return well to producing status. Rig down and move out pulling unit. Clean and clear location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE Sr. Staff Assistant DATE 04-25-95

TYPE OR PRINT NAME Terry L. Harvey TELEPHONE NO. 393-2144

(This space for State Use)

ORIGINAL SIGNED BY TERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAY 01 1995

CONDITIONS OF APPROVAL, IF ANY: