

## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

CORRECTED LOCATION

## NOTICE OF INTENTION TO DRILL

Notice must be given to the Oil Conservation Commission or its proper agent and approval obtained before drilling begins. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in triplicate. One copy will be returned following approval. See additional instructions in Rules and Regulations of the Commission.

Fort Worth, TexasJanuary 25, 1937

OIL CONSERVATION COMMISSION,  
Santa Fe, New Mexico

Gentlemen:

You are hereby notified that it is our intention to commence the drilling of a well to be known as \_\_\_\_\_

The Texas CompanyLee CookWell No. 1 in NE $\frac{1}{4}$  of NE $\frac{1}{4}$ 

Company or Operator

Lease

of Sec. 32, T. 19 S, R. 37E, N. M. P. M., Monument Field, Lea County.

N.

The well is 570 feet ~~EX~~ [S.] of the N line and 710 feet

~~EX~~ [W.] of the E line of NE $\frac{1}{4}$  of NE $\frac{1}{4}$  Section 32

(Give location from section or other legal subdivision lines. Cross out wrong directions.)

If state land the oil and gas lease is No. \_\_\_\_\_ Assignment No. \_\_\_\_\_

If patented land the owner is Lee Cook et ux

Address Monument, New Mexico

If government land the permittee is \_\_\_\_\_

Address \_\_\_\_\_

The lessee is The Texas Company

Address Box 2332, Houston, Texas

We propose to drill well with drilling equipment as follows: \_\_\_\_\_

Rotary

The status of a bond for this well in conformance with Rule 39 of the General Rules and Regulations of the Commission

is as follows: \$10,000.00 blanket surety bond of the U. S. Fidelity & Guaranty

Bond Co. has been filed with State Geologist. approximately \_\_\_\_\_

We propose to use the following strings of casing and to land or cement them/as indicated:

Size of Hole	Size of Casing	Weight Per Foot	New or Second Hand	Depth	Landed or Cemented	Sacks Cement
16"	13" OD	40#	Secondhand	150'	Cemented	150
12-1/4"	9-5/8" OD	40#	New	1390'	"	750
8-5/8"	7" OD	24#	"	3800'	"	350

If changes in the above plan become advisable we will notify you before cementing or landing casing. We estimate that the first productive oil or gas sand should occur at a depth of about 3875 feet.

Additional information: FORMATIONS EXPECTED:

Top of Salt 1410'  
Base of Salt 2460'  
Top of Main Brown Lime 2800'

Drilling operations to be commenced immediately.

Approved \_\_\_\_\_ 19 \_\_\_\_\_  
except as follows:

Subject to special regulations for drilling and casing wells in this area

Sincerely yours,

THE TEXAS COMPANY

Company or Operator

By [Signature]Position Asst. Division Manager

Send communication regarding well to

Name The Texas Company,Address Box 1720, Fort Worth, Texas.

OIL CONSERVATION COMMISSION,

By [Signature]Title Oil & Gas Inspector

RECEIVED

# REPORT OF INVESTIGATION

The purpose of this investigation was to determine the cause of the fire which occurred on the night of January 15, 1968, at the residence of Mr. and Mrs. John Doe, 123 Main Street, City, State. The fire caused the death of Mr. Doe and the injury of Mrs. Doe. The investigation was conducted by the Fire Department and the Police Department.

The fire was discovered by the Fire Department at approximately 10:30 p.m. on January 15, 1968. The fire was located in the living room of the residence. The fire was caused by a faulty electrical outlet.

The fire was caused by a faulty electrical outlet. The outlet was located in the living room of the residence. The outlet was found to be faulty by the Fire Department.

The fire was caused by a faulty electrical outlet. The outlet was located in the living room of the residence. The outlet was found to be faulty by the Fire Department.

The fire was caused by a faulty electrical outlet. The outlet was located in the living room of the residence. The outlet was found to be faulty by the Fire Department.

The fire was caused by a faulty electrical outlet. The outlet was located in the living room of the residence. The outlet was found to be faulty by the Fire Department.

The fire was caused by a faulty electrical outlet. The outlet was located in the living room of the residence. The outlet was found to be faulty by the Fire Department.

The fire was caused by a faulty electrical outlet. The outlet was located in the living room of the residence. The outlet was found to be faulty by the Fire Department.

The fire was caused by a faulty electrical outlet. The outlet was located in the living room of the residence. The outlet was found to be faulty by the Fire Department.

The fire was caused by a faulty electrical outlet. The outlet was located in the living room of the residence. The outlet was found to be faulty by the Fire Department.

The fire was caused by a faulty electrical outlet. The outlet was located in the living room of the residence. The outlet was found to be faulty by the Fire Department.

The fire was caused by a faulty electrical outlet. The outlet was located in the living room of the residence. The outlet was found to be faulty by the Fire Department.

The fire was caused by a faulty electrical outlet. The outlet was located in the living room of the residence. The outlet was found to be faulty by the Fire Department.

The fire was caused by a faulty electrical outlet. The outlet was located in the living room of the residence. The outlet was found to be faulty by the Fire Department.

The fire was caused by a faulty electrical outlet. The outlet was located in the living room of the residence. The outlet was found to be faulty by the Fire Department.

The fire was caused by a faulty electrical outlet. The outlet was located in the living room of the residence. The outlet was found to be faulty by the Fire Department.

The fire was caused by a faulty electrical outlet. The outlet was located in the living room of the residence. The outlet was found to be faulty by the Fire Department.

The fire was caused by a faulty electrical outlet. The outlet was located in the living room of the residence. The outlet was found to be faulty by the Fire Department.