Submit 3 Copies to Appropriate District Office	State of New M Energy inerals and Natural I	fexico Resources Department	Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATI	ON DIVISION	
DISTRICT	P.O. Box 20	88	WELL API NO. 30-025-05797
P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	87504-2088	S. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			STATE X FEE
			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			B-2330-10
(FORM	ROPOSALS TO DRILL OR TO DEEPE ERVOIR. USE "APPLICATION FOR P C-101) FOR SUCH PROPOSALS.)	N OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL QAS WELL X WELL	1		NORTH MONUMENT G7SA UNIT
2. Name of Operator	OTHER		<u>BLK. 16</u>
AMERADA HESS CORPOR	ATION		8. Well No.
3. Address of Operator POST OFFICE DRAWED			9. Pool name or Wildcat
	D, MONUMENT, NEW MEXICO		EUNICE MONUMENT G/SA
Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>SOUTH</u> Lipe and <u>1980</u> Feet From The <u>WEST</u> Line			
Section 32 Township 19S Range 37E NMPM LEA County			
10. Elevation (Show whether DF, RKB, RT, GR, etc.)			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
			
		REMEDIAL WORK	
PULL OR ALTER CASING		COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
OTHER: Intent to convert	to Inication 11 11 m	CASING TEST AND CE	
		OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. NMGSAU #1611			
Move in and rig up pulling unit, reverse unit and air unit. TOH with rods and pump. Nipple down wellhead. Nipple up BOP. TOH with tubing. TIH with underreamer, drill collars and tubing and underream f/3,807'-3,901'. TOH w/underreamer. Rig down air unit. Rig up Schlumberger and log the openhole with LDT/CNL/GR tools. Add perfora- tions based on new logs. Rig down Schlumberger. TH with transit			
to +/- 3,650'. Load casing-tubing annulus with fresh water. Set packer. Rig up acid company. Acidize well with 5,000 gal. 15% NEFE DI HCL w/3% DP-77MX Micellar solvent (using rock salt as diventing agent			
w/tubing and packer.	laving down production	as needed). Sw	ab/flow back load. TOH
injection tubing w/ir assembly. Rig down a	jection packer. Nippl and move out pulling un	e down BOP. Nip it. Clean and c	p and TIH w/2 3/8" coated ple up injection wellhead lear location
I hereby ceruly that the information above is tru	and complete to the best of my knowledge and	haline	K-4546,
SIONATURE		Staff Assis	tant .
TYPE OR HRINT NAME		LE JUATT ASSIS	DATE 10-24-94
	Terry Harvey	an a	TELEPHONE NO. 393-2144
DIST	Goled by Juery Sexton NCT I Supervision		OCT 28 1994
CONDITIONS OF APPROVAL, IF ANY:		2	DATE
ANY:			