

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name  LAUGHLIN
8. Well No. 2
9. Pool name or Wildcat EUNICE MONUMENT (G-SA)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator GRAHAM ROYALTY, LTD.
3. Address of Operator 5429 LBJ FREEWAY, STE 550 DALLAS, TX 75240	4. Well Location Unit Letter <u>O</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line Section <u>5</u> Township <u>20S</u> Range <u>37E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU Smith Brothers Plugging Co. POH w/rods & tbq.  
Set 7" CIBP @ 3550'. Cap w/5 sacks cmt. Displaced hole w/9.5 ppg mud-laden fluid.  
Spot 30 sx cmt plug from 2670'-2520'. Shot 7" csg @ 335'. Pump down 7" csg  
w/good returns out 12½" csg. M&P 135 sx cmt. Pump down 7" csg w/good  
returns out 12½" csg. Displace to 175' inside 7" csg. Cut off csg head.  
Spot 5 sx cmt plug at surface. Weld on steel plate. Erect dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE JACK D. BLEDSOE TITLE PROD. SUPT. DATE 4/19/89

TYPE OR PRINT NAME JACK D. BLEDSOE TELEPHONE NO. 915/686-8646

(This space for State Use)

APPROVED BY R. A. Lally OIL & GAS INSPECTOR AUG 21 1989  
TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

100-100000

100-100000

RECEIVED

APR 20 1989

OCD  
HOBBS OFFICE