Form 9-331 UNITE TATES SUBMIT IN TRIPLICAT (Other instructions on DEPARTMENT Or THE INTERIOR verse side)	-) Form approved. Budget Bureau No. 42-R1424.
GEOLOGICAL SURVEY	LC-031621 (a)
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.	7. UNIT AGREEMENT NAME
OIL GAS WELL X WELL OTHER	Britt "A" Unit
2. NAME OF OPERATOR	S. FARM OR LEASE NAME
UNION TEXAS PETROLEUM CORPORATION	Britt "A"
3. ADDRESS OF OPERATOR	9. WELL NO.
1300 Wilco Building, Midland, Texas 79701	7
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements,* See also space 17 below.) 	10. FIELD AND POOL, OR WILDCAT
At surface	Monument
	11. SEC., T., R., M., OB BLK. AND SURVEY OR ABEA
Unit Letter "K", 2310' FSL & 1880' FWL	Sec. 6, T-20-S, R-37-E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
3570' DF	Lea New Mexico
^{16.} Check Appropriate Box To Indicate Nature of Notice, Report, or	Other Data
NOTICE OF INTENTION TO :	QUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE X ABANDON* SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL CHANGE FLANS X (Other)	
(Other) (Note: Report resu	ts of multiple completion on Well apletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dat proposed work. If well is directionally drilled, give subsurface locations and measured and true very nent to this work.) *	
The following is an amended procedure of the original	• · · · · · · ·

approval with our Mr. Tom Walton on July 13, 1977.

- 1. MIRUPU Install BOP.

- Mikoro Install bor.
 Spot 100' plug on top of Model "D" packer.
 Set cement retainer @ 7000' and squeeze casing leaks 7000'-8292'.
 Load hole with 2% KCL water containing 1 gallon of Morflo II per 1000 gallons
 Pull out of hole w/tubing and perforate Paddock zone 5145-5165'
 Acidize perforations w/1500 gallons 15% NE Acid.

- 7. Fracture treat well if needed.
- 8. Clean up well as neeedd and install production equipment.
- 9. Place well back on production.

18. I hereby certify that the foregoing is true and correct SIGNED	TITLE Sr. Prod. Analyst
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	
	e Instructions on Reverse Side