## KICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent of the plan submitted. The plan as approved should be followed, and work should not begin used and work should be followed. or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See addi-

		Indicate Nature of	f Notice by Ch	ecking Belo	w	=	
Notice of Intention to Change Plans		Notice of Intenti Temporarily Aban	on to NDON WELL		Notice of Intenti to Drill Deeper	ION	
Notice of Intention to Plug Well		Notice of Intenti	ION	*	Notice of Intenti to Set Liner	ion	
Notice of Intention to Squeeze		Notice of Intenti to Acidize	ION	x	NCTICE OF INTENT	ION	
Notice of Intention to Gun Perforate		Notice of Intenti (Other)	ion		Notice of Intent (Cther)	ion	
OIL CONSERVATION SANTA FE, NEW MEX		Hobbs	New Mex (Place)	iso		April 27,	1956
Gentlemen: Following is a Notic	ce of Intention to do	certain work as desc	ribed below at	the			
Gulf Oil Corpor							
NR 1/4 NR	(Company or Operator)	, T. 20-S	, R. <b>37-E</b>	,NMPM.,	Monument	Blinebry	Peol
(40-acre Subdivision)	Cour						
					EGULATIONS)		
	Pull rods, pu Drill out Hyd Run wireline Run tubing, s	mp and tubing romite plug t squeeze cemen	6. 5705'. it tool, p	plug be	ck and acidia	se as follo	ws:
1. 2. 3.	Pull rods, pu Drill out Hyd Run wireline	mp and tubing romite plug t squeeze cemen	6. 5705'. it tool, p	plug back	ck and acidia	a <b>tîpn</b>	ws:
1. 2. 3. 4.	Pull rods, pu Drill out Hyd Run wireline	mp and tubing romite plug t squeeze cemen	5. 5705. at tool, p	plug back lug back Gui	to 5685'.  Company or Operation of the Company of Operation of the Communications regularity and the Communication regu	ation  atom  atom  of Prod.  arding well to:	<b>W8</b> :
ApprovedExcept as follows:	Pull rods, pur Drill out Hydraun wireline Run tubing, s	mp and tubing romite plug t squeeze cemen	5. 5705	plug back lug back Gui	to 5685'.  Company or Operation of Area Supt.	ation  atom  atom  of Prod.  arding well to:	ws: