STATE OF NEW! MEXICO ENERGY AND MINERALS DEPARTMENT

	_,	
HD. DF COPIES RECEIVED	1	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.3.		
LAND OFFICE		
OPERATOR		

C.L CONSERVATION DIVISION P. O. BOX 2088

Form C-103

SANTA FE	SANTA FE, NEW	MEXICO 87501		Revised 10-1-78
FILE			5a. Indicate Ty	pe of Lease
U.S.O.3.			State	Fee X
LAND OFFICE				
OPERATOR			5. State Off & 0	Gas Lease No.
SUNDRY NOTICE THIS FORM FOR PROPOSALS TO I	ES AND REPORTS ON A	WELLS CK TO A DIFFERENT RESERVOIR. PROPOSALS.)		
1.			7. Unit Agreem	ent Name
OIL CAS WELL OTHER-			-	
2. Name of Operator			8. Form or Lea	
TEXACO Inc.			J. R. Phi	Hips
3. Address of Operator			9. Well No.	
P. O. Box 723, Hobbs, Ne	ew Mexico 88240		6	
4. Location of Well			10. Field and F	Pool, or Wildcat
E 660	West	1897	Monument	Abo
UHIT LETTER	FEET FROM THE	LINE AND F	EET FROM	rmm
North	30-5	37-F		
North Line, section (TOWNSHIP	HANGE	NMPM. \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
	15. Elevation (Show whether I	OF, RT, GR, etc.)	12. County	
	3576' (DF)	l_ea	_//////////////////////////////////////
16. Check Appropris	ate Box To Indicate Na	sture of Notice Repor	t or Other Data	
NOTICE OF INTENTIO			EQUENT REPORT OF	: •
NOTICE OF INTENTIO	N 10.	, 30632	EQUENT REPORT OF	•
	PLUG AND ABANDON	REMEDIAL WORK	M	ERING CASING
PERFORM REMEDIAL WORK	PEDE NIO XBANDON		<u>k</u> —	<u></u>
TEMPORARILY ABANDON		COMMENCE DRILLING OPHS.		AND ABANDONMENT
PULL OF ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JQB		
		OTHER		
OTHER				
				
17. Describe Proposed or Completed Operations (C	learly state all pertinent detail	ils, and give pertinent dates,	including estimated date o	f starting any propose:
work) SEE RULE 1103.				

- 1.
- RIGGED UP. PULL RODS AND PUMP. INSTALL BOP. PULL TUBING. SET PKR @ 7039'. ACIDIZE PERFS 7108' 7710' W/7000 GALS 15 % LST NEFE ACID AND 4100# SALT IN 5-STAGES.
- CLEAN OUT

		A: SIGNED BY	JERRY SEXTO						MAY 3 1984
s:4+ 6 0	64	Ann &		Asst	Dist				DATE 5-1-84
15. I hereby ce	rtify that the	Info-matton abov	e is true and c	omplete to the best of	my knowl	edge an	d belief.		
•		•							
		•							
	4.	INSTALL	PUMPING	EQUIPMENT.	TEST	AND	PLACE	UN	FRODUCTION.