

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-05962
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name J.R. Philips
8. Well No. 9
9. Pool name or Wildcat Eumont Yates Seven Rivers Qn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Texaco Exploration and Production Inc.
3. Address of Operator P.O. Box 730 Hobbs, New Mexico 88240	4. Well Location Unit Letter C : 990 Feet From The North Line and 1931 Feet From The West Line Section 6 Township 20S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3574' DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OF NS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1.) Notify OCD 24 hours prior to commencement of plugging operations.
- 2.) MIRUPU. TIH w/ 4 3/4" bit. Drill out cmt and CIBP @ 3130'. (CIBP @ 3150').
- 3.) TIH w/ 5 1/2" cmt rtn. and set @ +/- 3150'. Sqz Eumont perms w/ 100 sxs Class "C" cmt. Sting out of retainer leaving 35' cmt on top.
- 4.) Cut and pull 5 1/2" csg @ 1225'. Set 150' (32 sxs) cmt plug from 1275' to 1125'. WOC. Tag Plug.
- 5.) Perforate 2 sqz holes @ 350'. Sqz perms w/ 240 sxs Class "C" cmt.
- 9.) Cut off wellhead. Install hole marker. Clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. C. [Signature] TITLE Engineer's Assistant DATE 10-07-91

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use) **SIGNED BY JERRY SEXTON**
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: