

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.		

## SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator GRAHAM ROYALTY, LTD.	8. Farm or Lease Name ALASKA COOPER
3. Address of Operator 5429 LBJ FREEWAY, SUITE 550 DALLAS, TX 75240	9. Well No. 2
4. Location of Well UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>NORTH</u> LINE AND <u>660</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>7</u> TOWNSHIP <u>20S</u> RANGE <u>37E</u> N.M.P.M.	10. Field and Pool, or Wildcat EUNICE MONUMENT (G-S)
15. Elevation (Show whether DF, RT, GR, etc.)	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:  
REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/4/88 MIRU PERMIAN BASIN CASING PULLERS. TOH w/ 2 3/8" tbq sub. TIH w/7" CIBP on 2 7/8" work string. Set CIBP @ 3466'. (witness and approved by NMOCC.)

8/5/88 Displace hole w/9.5 ppg mud-laden fluid. Spot 5 sx cmt on CIBP @ 3466'. Spot 25 sx cmt plug from 2450'-2300'. Perf 7" csg @ 305'. Establish circulation. Spot 40 sx cmt plug inside and outside 7" csg from 305' - 200'. Cut off well head. Spot 5 sx surface plug. Weld on steel plate. Install dry hole marker. Clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jack D. Beedsae

TITLE Production Superintendent

DATE 8/22/88

APPROVED BY R. A. Hall

TITLE OIL & GAS INSPECTOR

DATE MAY 1 1989

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 28 1998

OCD  
HOBBS OFFICE