

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN THIS
(Check Instruction
Box Below)

Form approved
Bureau No. 42-11424
B. LEAD DESIGNATION AND SERIAL NO.

LC 031621 (a)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR UNION TEXAS PETROLEUM CORPORATION		8. FIRM OR LEASE NAME Britt	
3. ADDRESS OF OPERATOR 1300 Wilco Building, Midland, Texas 79701		9. WELL NO. 2	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface		10. TIERED AND PROD. OR WILDCAT Monument-Grayburg	
11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Unit Letter "C", 660' FNL & 1980' FWL		12. COUNTY OR PARISH Lea	
13. PERMIT NO.		13. STATE New Mexico	
14. ELEVATIONS (Show whether DP, RT, CR, etc.) 3563' GL			

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data


NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☒	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. RU and re-enter well. Install BOP.
2. Set CIBP @ 3750'
3. Perforate Grayburg Zone with 1 JSPF 3453, 70, 86, 93, 95, 3514, 16, 18, 20, 32 & 38'.
4. PU and RIH w/Guiberson Uni-Pkr. III on 2 3/8" tubing and set @ 3420'.
5. Acidize well with 4000 gallons 15% NE Acid.
6. Swab back acid water and put well back on production.

18. I hereby certify that the foregoing is true and correct

SIGNED 

TITLE Sr. Prod. Analyst

DATE 2-1-77

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

