Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

1.1. P.C ... 37

Jan 3 144

5. Lease Designation and Serial No. LC-031621A

o not use this form for proposals to drill o Use "APPLICATION FOR	PERMIT-" for skilligh yorg posals—	ς
SUBMIT IN TRIPLICATE REAU OF LAND 143717. 1. Type of Well Gas Well Other		7. If Unit or CA, Agreement Designation
. Type of Well	MOBBS, NEW MEXICO	11.
Oil Gas Well Other		8. Well Name and No.
2. Name of Operator		-H:M . Britt No. 4
Doyle Hartman		9. API Well No.
3. Address and Telephone No.		30-025-05992
P.O. Box 10426, Midland, TX 79702-7426		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 660' FNL & 1980' FEL (Unit B), Section 7, T-20-S, R-37-E		Eunice Monument 11. County or Parish, State
		Lea County, NM
CHECK APPROPRIATE BOX(s) T	O INDICATE NATURE OF NOTICE, RE	PORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
X Notice of Intent	Abandonment	Change of Plans
Motice of linear	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other Test Casing / Temporarily A	
 Describe Proposed or Completed Operations (Clearly state directionally drilled, give subsurface locations and measure Move in, rig up and pull tubing and packer. Set retainer at +/- 3670'. Load casing with non-corrosive fluid and test If the casing integrity is good then well will be 	all pertinet details, and give pertinent dates, including end and true vertical depths for all markders and zones per casing for integrity. Repair or P&A if necessa	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) estimated date of starting any proposed work. If well is itinent to this work.)*
directionally drilled, give subsurface locations and measure 1. Move in, rig up and pull tubing and packer. 2. Set retainer at +/- 3670'. 3. Load casing with non-corrosive fluid and test	all pertinet details, and give pertinent dates, including end and true vertical depths for all markders and zones per casing for integrity. Repair or P&A if necessa	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) estimated date of starting any proposed work. If well is trinent to this work.)* If y. eccompletion potential.
directionally drilled, give subsurface locations and measure 1. Move in, rig up and pull tubing and packer. 2. Set retainer at +/- 3670'. 3. Load casing with non-corrosive fluid and test	all pertinet details, and give pertinent dates, including end and true vertical depths for all markders and zones per casing for integrity. Repair or P&A if necessa	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) estimated date of starting any proposed work. If well is itinent to this work.)* APPROVED PETER W. CHESTER
 Move in, rig up and pull tubing and packer. Set retainer at +/- 3670'. Load casing with non-corrosive fluid and test 	all pertinet details, and give pertinent dates, including end and true vertical depths for all markders and zones per casing for integrity. Repair or P&A if necessa	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) estimated date of starting any proposed work. If well is it inent to this work.)* APPROVED PETER W. CHESTER MAY 2 4 1999
directionally drilled, give subsurface locations and measure 1. Move in, rig up and pull tubing and packer. 2. Set retainer at +/- 3670'. 3. Load casing with non-corrosive fluid and test	all pertinet details, and give pertinent dates, including end and true vertical depths for all markders and zones per casing for integrity. Repair or P&A if necessa	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) estimated date of starting any proposed work. If well is itinent to this work.)* APPROVED PETER W. CHESTER
1. Move in, rig up and pull tubing and packer. 2. Set retainer at +/- 3670'. 3. Load casing with non-corrosive fluid and test 4. If the casing integrity is good then well will be 14. I hereby certify that the foregoing is true and correct Signed	all pertinet details, and give pertinent dates, including end and true vertical depths for all markders and zones per casing for integrity. Repair or P&A if necessa	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) estimated date of starting any proposed work. If well is it inent to this work.)* If y. ecompletion potential. APPROVED PETER W. CHESTER MAY 2 4 1999
1. Move in, rig up and pull tubing and packer. 2. Set retainer at +/- 3670'. 3. Load casing with non-corrosive fluid and test 4. If the casing integrity is good then well will be	all pertinet details, and give pertinent dates, including end and true vertical depths for all markders and zones per casing for integrity. Repair or P&A if necessatemporarily abandoned in order to evaluate response	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) estimated date of starting any proposed work. If well is intenent to this work.)* If y. ecompletion potential. APPROVED PETER W. CHESTER MAY 2 4 1999 BUREAU OF LAND MANAGEME ROSWELL RESOURCE AREA
1. Move in, rig up and pull tubing and packer. 2. Set retainer at +/- 3670'. 3. Load casing with non-corrosive fluid and test 4. If the casing integrity is good then well will be 14. I hereby certify that the foregoing is true and correct Signed (This space for Federal or State office use)	all pertinet details, and give pertinent dates, including end and true vertical depths for all markders and zones per casing for integrity. Repair or P&A if necessatemporarily abandoned in order to evaluate response	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) estimated date of starting any proposed work. If well is intenent to this work.)* If y. ecompletion potential. APPROVED PETER W. CHESTER MAY 2 4 1999 BUREAU OF LAND MANAGEME ROSWELL RESOURCE AREA
1. Move in, rig up and pull tubing and packer. 2. Set retainer at +/- 3670'. 3. Load casing with non-corrosive fluid and test 4. If the casing integrity is good then well will be 14. I hereby certify that the foregoing is true and correct Signed (This space for Federal or State office use)	all pertinet details, and give pertinent dates, including end and true vertical depths for all markders and zones per casing for integrity. Repair or P&A if necessatemporarily abandoned in order to evaluate response to the control of the control	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) estimated date of starting any proposed work. If well is itinent to this work.)* ITY. ecompletion potential. PETER W. CHESTER MAY 2 4 1999 BUREAU OF LANC MANAGEME ROSWELL RESOURCE AREA Date 05/03/99

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N 'Oil Ce 5 1986 Hobbe NALSee

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

	Hobbs, NM 38241	5. Lease Designation and Serial No. LC-031621A	
Do not use this form for proposals to dril	AND REPORTS ON WELLS I or to deepen or reentry to a different reservoir. R PERMIT-" for such proposals	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE 1. Type of Well		7. If Unit or CA, Agreement Designation	
Oil Gas Well Well Other		8. Well Name and No.	
2. Name of Operator		H. Britt No. 4	
Doyle Hartman, Oil Operator 3. Address and Telephone No.		9. API Well No.	
P. O. Box 10426, Midland, TX 79702 915-684-4011		30-025-05992 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Eunice Monument	
660' FNL & 1980' FEL (Unit B) Section 7, T-20-S, R-37-E		11. County or Parish, State	
		Lea County, NM	
12. CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REPORT, O	R OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent	Abandonment	Change of Plans	
	Recompletion	New Construction	
Subsequent Report	☐ Plugging Back☐ Casing Repair	☐ Non-Routine Fracturing	
Final Abandonment Notice	☐ Altering Casing	☐ Water Shut-Off ☐ Conversion to Injection	
	Other	☐ Dispose Water	
		(Note: Report results of multiple completion on Weil Completion or Recompletion Report and Log form.)	
 Describe Proposed or Completed Operations (Clearly sta directionally drilled, give subsurface locations and measu We intend to recomplete this well to the Eum 	ite all pertinet details, and give pertinent dates, including estimated date or red and true vertical depths for all markders and zones pertinent to this wont. Gas Pool using the follwing procedure:	of starting any proposed work. If well is ork.)*	
1. Clean out well to +/- 3800'	TA expired 4/3/95		
2. Set CIBP @ +/- 3800'	NO CITI	_	
3. Integrity test casing and repair if necessar	у	8UR -	
4. Perforate and acidize Eumont		RE(1991 SEI 198E AU HOBBS	
5. Install rod-pump equipment		· o · o · O	
6. Evaluate well for possible frac job		EIVE 24 A 7 F LAND NEW ME.	
Pending rig and other equipment availability we plan to commence this work in the next 4 to 6 months			
not, a casing integral or well plugged as	ted within 6 months, y ity test must be done and abandoned.	/ED A 8: 36 ND MGMT. MEXICO	
14. I hereby certify that the foregoing is tode end correct Signed	Title Engineer	Date 09/22/97	
(This space for Federal or State office use)			
Approved by Conditions of approval, if any:	Title	Date Control to the c	