

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-06043
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	L. Van Etten
8. Well No.	3
9. Pool name or Wildcat	Eunice Monument GBSA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	
2. Name of Operator Texaco Producing Inc.	
3. Address of Operator P. O. Box 730 Hobbs, NM 88240	
4. Well Location Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line Section 9 Township 20S Range 37E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3548 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1.) Notify OCD 24 hours prior to commencement of plugging operations.
- 2.) MIRUPU. Set 7" CIBP at 3500' and dump 35' (7 sxs) of cement (Class "H" w/ 2% CaCl₂, 5.2 gal/sack, 15.6 ppg, 1.18 cu. ft/sack) on top of plug. Load hole w/ 9.5 ppg mud.
- 3.) Spot 200' cement plug from 1000' to 1200'. (38 sxs Class "H" w/ 2% CaCl₂, 1.18 cu ft/sack)
- 4.) Spot 132' cement plug from 79' to 211'. (25 sxs Class "H" w/ 2% CaCl₂, 1.18 cu ft/sack)
- 5.) Spot 53' cement plug from 53' to surface. (10 sxs Class "H" w/ 2% CaCl₂, 1.18 cu ft/sack)
- 6.) Cut off wellhead. Install hole marker. Clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Larry D. Ridenour TITLE Engineer's Assistant DATE 11-21-90
TYPE OR PRINT NAME Larry D. Ridenour

TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____

TO BE APPROVED.