

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Sun Oil Company		8. Farm or Lease Name H. D. McKinley	
3. Address of Operator P. O. Box 1861, Midland, Texas 79701		9. Well No. 6	
4. Location of Well UNIT LETTER A , 585 FEET FROM THE North LINE AND 585 FEET FROM THE East LINE, SECTION 5 TOWNSHIP 19S RANGE 38E NMPM. Bowers		10. Field and Pool, or Wildcat	
15. Elevation (Show whether DF, RT, GR, etc.) 3620 GR		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1.) MIRU
- 2.) Pick up 2" work string and run in hole. Circulate hole with 9.5# mud
- 3.) Spot 40 sx. cmt. plug 3165 - 3060, pull tbq.
- 4.) Run free point, shoot and pull 5-1/2" csg.
- 5.) Run 2" tbq., spot 20 sx. plug 50' in and out of 5-1/2" csg. stub.
- 6.) Spot 35 sx. cmt. plug 340 - 240 across 9-5/8" csg. seat.
- 7.) Spot 10 sx. cmt. plug at surface, weld cap on 9-5/8" csg., install marker.

10 c' plugs

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Charles Gray</i></u>	TITLE <u>Proration Clerk</u>	DATE <u>1-15-74</u>
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		