accordance with calculation tables. No gas was encountered in the Brown Lime, which was largely anhydrite. In fact, we encountered anhydrite in this well as deep as 2850 feet. The top of the Ramsay as encountered at 8525 feet, so that no gas producing formation is open above the cament.

I regret that this error cropped into our operations, yet since no damage should result from the present construction of the well, I do not feel that the company should be required to repair the well. Please advise your reaction unofficially, and I will see that the thing is carried through in the proper manner later.

Yours very truly,

LLG:FS