Form 9-331 May 1963)	UNITED STATES SUBMIT IN TRIPLICA (Other instructions on	TE* Budget Bure 5. LEASE DESIGNATION	AND SERIAL NO.	
	DEPARTMENT OF THE INTERIOR (Other Instructions on	LC-066126		
	GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTT	EE OR TRIBE NAME	
(Do n	SUNDRY NOTICES AND REPORTS ON WELLS not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	7. UNIT AGREEMENT 1	(AME	
1. oil V	gas [
WE'LL A	WELL OTHER	8. FARM OR LEASE NA	AME	
		Hanson D		
3. ADDRESS C	Burk Royalty Co.	9. WELL NO.		
	P. O. Box BRC, Wichita Falls, TX 76307 OF WELL (Report location clearly and in accordance with any State requirements.*	10. FIELD AND POOL,	10. FIELD AND POOL, OR WILDÇAT	
4. LOCATION See also s At surfac	space 1 (below.)		Lynch Yates 7 River	
	Unit Letter D, 330 ft. INL, 330 FWL,	11. SEC., T., R., M., OI SURVEY OR AR	11. SEC., T., R., M., OB BLK. AND SURVEY OR ABEA	
	Sec. 26, T20, R34NMPM.	S26T20R34		
2	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARI	SH 13. STATE	
14. PERMIT N	KB 3694'; GR 3682.7'	Lea	NM	
	Check Appropriate Box To Indicate Nature of Notice, Report,	or Other Data		
16.		BSEQUENT REPORT OF:		
	WATER SHUT-OFF	REPAIRING	WELL	
	ATER SHUT-OFF PULL OR ALTER CASING RE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING	CASING	
	OR ACIDIZE ABANDON* X SHOOTING OR ACIDIZING	ABANDON	MENT*	
REPAIR	WELL CHANGE PLANS (Other) (Note: Report r	esults of multiple completic ecompletion Report and Log	on on Well	
(Other)	Completion of Rose Proposed or Complete Operations (Clearly state all pertinent details, and give pertinent sed work. If well is directionally drilled, give subsurface locations and measured and true		into of otosting any	
nent a	3728' 5 1/2" 8 shots from 6 shots from 6 shots from	ecord: 3614' to 3618' 3620' to 3624' 3628' to 3631'		
	Proposed Plugging Procedure: Pump a 100 sxs. cemtbg top of plug at 3500. Set cement retainer at cmt. (90 sxs. below cement retainer w/10 sxs. above pump 100 sxs. cement (70 sxs. out. 30 sxs. in). Feirculate 100 sxs. cement back to surface. Cut pipe	e). Perforate a	800', arid	
	level, weld on cap and bury.	ת	٠c %	
	11) at achamatic	, in the second	SEP 7	
*P	please see attached schematic.	- 1	REC	
			CEIVED	
		•	WE VE	
		ŗ.		
18. I hereb	by certify that the foregoing is true and correct		100 N	
SIGNE	Robert Fowler, Vic	ce Pres. DATE	9/22/87	
	space for Federal or State office use)		. 63	
	mini E	DATE	011/	
CONDI	OVED BYITILEIT			