

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
----------------------------	------------------------------------------------------------------------

5. State Oil & Gas Lease No.	LG-3691
------------------------------	---------

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator V.H. Westbrook	8. Farm or Lease Name State BI
3. Address of Operator P.O. Box 2264 Hobbs, N.M. 88240	9. Well No. 1
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 2180 FEET FROM THE West LINE, SECTION 9 TOWNSHIP 19S RANGE 36E N.M.P.M.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3792.3	12. County Lea

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Run in Hole w/Tubing. Spot 25 sk plug at 4920 in 4 1/2"
2. WOC + Tag
3. Circulate hole w/Mud laden Brine
4. Pull up + spot 40 sk plug in 9 5/8" at 1700'
5. Cut off well-head. Pump 10 sk plug at surface + install dry Hole Marker
6. Clean-up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H.A. Westbrook TITLE Operator DATE Oct. 9, 1985

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR

TITLE

DATE OCT 9 - 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT -9 1985

O.C.D.  
HOBBS OFFICE