

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 3691	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator		8. Farm or Lease Name	
V. H. Westbrook		State BI	
3. Address of Operator		9. Well No.	
P.O. Box 2264, Hobbs, NM 88240		#1	
4. Location of Well		10. Field and Pool, or Wildcat	
UNIT LETTER <u>F</u> , 1980 FEET FROM THE <u>North</u> LINE AND <u>2180</u> FEET FROM		Wildcat	
THE <u>West</u> LINE, SECTION <u>9</u> TOWNSHIP <u>19S</u> RANGE <u>36E</u> NMPM.			
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
3792.3		Lea	

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-19-81 Set CIBP @ 8650' Run 35' cement on top of CIBP.  
Cut 4½ liner off @ 7750. Pull 3500' liner.  
Set 100' cement plug at 7750' to 7650' - 50' in pipe 50' out pipe.  
Set 100' plug at 6100' to 6000.  
Set 100' plug at 5200' to 5100' w/Jelled brine between all plugs.  
Run 4½ J-55 liner to 5100' - Hang from 9 5/8 at 4100'  
Cement w/300 sks - back into 9 5/8. Perforate from 4920' to 4930' w/ 2 shts per ft.  
Acidize w/ 500 gals. Acid - Swab test well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Janet S. Brooke</u>	TITLE <u>Office Manager</u>	DATE <u>10-18-81</u>
APPROVED BY <u>[Signature]</u>	TITLE <u></u>	DATE <u>OCT 27 1981</u>
CONDITIONS OF APPROVAL, IF ANY:		