

SUNDRY NOTICES AND REPORTS ON WELLS

Page 2

Aztec 14 Federal No. 2

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS.

7. Spot 100' plug across 8-5/8" cut-off using tbg. 1950 to 2050, with 50 sxs. cement. (50' in and 50' out)
8. Spot 100' plug across 13-3/8" shoe 600 to 700' with 75 sx. cement.
9. Spot 100' plug @ surface using 75 sxs.
10. Weld on plate and erect dryhole marker.
11. Remove surface equipment and restore location.