DISTRIBUTION BANTA FE	OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501		Form C-103 Revised 10-
FILE U.S.O.S. LAND OFFICE OPERATOR	SANTATE, NEW		5a. Indicate Type of Lease State 5. State Oil & Gas Lease No.
SUNDRY NOTICE DO NOT USE THIS FORM FOR PROPOSALS TO THE USE "APPLICATION FOR PERMI	SAND REPORTS ON A DEFENSION OF PLUG DA	WELLS CN TO A DIFFERENT RESERVOIN. I PROPOSALS.]	
OIL X GAN OTHER-			7, Unit Agreement Name 8. Farm or Lease Name
Amoco Production Company			South Hobbs GSA Un 9. Well No.
P. O. Box 68, Hobbs, NM 88	3240		123 10. Field and Pool, or Wildcat
	ET FROM THE North		Hobbs GSA
THE East LINE, SECTION 6			 12. County
	5. Elevation (Show whether)		Lea
Check Appropriat		ature of Notice, Repor SUBSE	t or Other Data Equent report of:
RFOIM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
INFORABILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
OTHER	CHANGE PLANS	CASING TEST AND CEMENT JQ8	
	filed 8-11-80. at 4050'. Squeez Class C cement. ated interval 405 0'. Pump 1000 ga	casing test and cement job other tils, and give pertinent dates, Run bit and drill of 4'-4066' with 4 JSI llons of ASOL acid	4098'-4106' and out cement retainer PF. Run tubing and tagged with
OTHER Describe Proposed or Completed Operations (Cla work) see RULE 1703. Supplemental brief to C-103 Run cement retainer and set 4110'-24' with 250 sacks of and cement to 4115'. Perfor packer and set packer at 400 Radioactive Iodine. Pull tu	filed 8-11-80. at 4050'. Squeez Class C cement. ated interval 405 0'. Pump 1000 ga	casing test and cement job other tils, and give pertinent dates, Run bit and drill of 4'-4066' with 4 JSI llons of ASOL acid	4098'-4106' and out cement retainer PF. Run tubing and tagged with
OTHER Describe Proposed or Completed Operations (Clawork) SEE RULE 1103. Supplemental brief to C-103 Run cement retainer and set 4110'-24' with 250 sacks of and cement to 4115'. Perfor packer and set packer at 400 Radioactive Iodine. Pull tu to production.	filed 8-11-80. at 4050'. Squeez Class C cement. ated interval 405 0'. Pump 1000 ga bing and packer.	casing test and cement job other tils, and give pertinent dates, Run bit and drill of 4'-4066' with 4 JSI llons of ASOL acid	4098'-4106' and out cement retainer PF. Run tubing and tagged with
other Describe Proposed or Completed Operations (Cle work) SEE RULE 1163. Supplemental brief to C-103 Run cement retainer and set 4110'-24' with 250 sacks of and cement to 4115'. Perfor packer and set packer at 400 Radioactive Iodine. Pull tu to production.	filed 8-11-80. at 4050'. Squeez Class C cement. ated interval 405 O'. Pump 1000 ga bing and packer.	CASING TEST AND CEMENT JQB OTHER iils, and give pertinent dates, Run bit and drill of 4'-4066' with 4 JSI llons of ASOL acid Install pumping ed	4098'-4106' and out cement retainer PF. Run tubing and tagged with

ONDITIONS OF	APPROVAL.	1 F	AN
ł			

NIG NOILVANISHOO 710

. .

•

.

- -

. **.** .

18. 01 NAA

CEVED39