

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-26674
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Gulf Huston
2. Name of Operator Tierra Operating Co.	8. Well No. # 1
3. Address of Operator P.O. Box 2188 Hobbs, New Mexico 88241	9. Pool name or Wildcat Eumont- Yates 7 Rs Queen
4. Well Location Unit Letter <u>B</u> : <u>660'</u> Feet From The <u>North</u> Line and <u>1980'</u> Feet From The <u>East</u> Line Section <u>7</u> Township <u>19S</u> Range <u>37E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3716 GL.	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pulled 3304' of tubing, went back in hole with tubing and bit tagged fish at 3304'. Pulled tubing and bit, received permission from OCD to set CIBP at 3304'.
2. Went in hole with CIBP on tubing set CIBP at 3304', displaced hole with Gelled Brine.
3. Set 35' plug on top of CIBP, pulled tubing to 1556' set 100' plug from 1556' to 1456', pulled tubing set a 10 Sx. plug at surface. Dug out cellar cut off well Head rigged down well service unit, cut of anchors, installed dry hole marker, cleaned location FRW.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joe T. Janica TITLE President DATE 08/21/95
TYPE OR PRINT NAME Joe T. Janica TELEPHONE NO. 505-392-2112

(This space for State Use)

APPROVED BY Larry M. Hill TITLE Director DATE 3-17-97
CONDITIONS OF APPROVAL, IF ANY:

IC

dd

PL-515

AUG 2 1964

U.S. AIR FORCE
OFFICE