

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-27061
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Watkins "A"
2. Name of Operator Mitchell Energy Corporation	8. Well No. 1
3. Address of Operator PO Box 4000; The Woodlands, TX 77387-4000	9. Pool name or Wildcat Featherstone (Bone Spring)
4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>22</u> Township <u>20North</u> Range <u>35 East</u> NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3694

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POOH w/±13,000' 2-3/8" 4.7# N-80 tbg. Set CIBP @ 10,300' w/35' cement on top. Displace hole w/9.5 ppg mud. Cut 7-5/8" csg @ ±3200' & POOH w/csg. RIH w/tbg and spot 100' plug across 10-3/4" shoe @ 4303'. Tag plug. Pickup and spot 100' plug across csg cut @ ±3200'. Tag plug.

POOH and spot 10 sx surface plug. Cut off csg head & place P&A marker on site.
Clean location.

100' cement plug @ 7000'
100' cement plug @ 450'-356'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Sr. Engineering Technician DATE 1-30-97
TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY [Signature] ORIGINAL SIGNED BY JERRY SEXTON
DATE FEB 17 1997

CONDITIONS OF APPROVAL, IF ANY.

JC dp

Watkins "A" #1
Featherstone (Bone Spring)
Unit C, S22, T20S, R35E
Lea Co., NM
JGC 1-8-94

Present

KB: 3714.8'
GL: 3693.8'

