

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5a. Indicate Type of Lease State ☐ Fee ☒
2. Name of Operator <i>Amoco Production Company</i>	5. State Oil & Gas Lease No.
3. Address of Operator <i>P.O. Box 68, Hobbs, NM 88240</i>	7. Unit Agreement Name
4. Location of Well UNIT LETTER <i>F</i> <i>1785</i> FEET FROM THE <i>North</i> LINE AND <i>1810</i> FEET FROM THE <i>West</i> LINE, SECTION <i>5</i> TOWNSHIP <i>19-S</i> RANGE <i>38-E</i> N.M.P.M.	8. Farm or Lease Name <i>McKinley</i>
	9. Well No. <i>20</i>
	10. Field and Pool or Wildcat <i>Bowers Seven Rivers</i>
15. Elevation (Show whether DF, RT, GR, etc.) <i>3621.1 GL</i>	12. County <i>Lea</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <i>recomplete as injection well</i> ☒	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to deepen and recomplete as a San Andres injection well after abandoning the Bowers as follows:
MSU. Pull rods, pump, tbg and tbg anchor. RIH with cmr retainer and set at 3000'. Pump 100 sx Class C Heat cmr. String out of retainer, reverse out excess cmr and POH. Drill out cmr retainer and cmr to 3230'. Drill out remaining cmr, float collar, float shoe to 3800'. Circulate clean. Deepen to TD of 4300'. Circulate clean. Run logs. RIH with guide shoe, float collar and csq. Tag TD and pull up 1 ft. Circulate for 2 hrs while reciprocating - 10-15 ft. Pump 500 sx Class C Heat. Drop plug and displace with 68 bbls
O+5-NMOCB, H 1-JRB 1-FJN 1-BFC

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Bonita Able* TITLE *Administrative Analyst* DATE *9-27-84*

APPROVED BY *Eddie W. Seay* TITLE *Oil & Gas Inspector* DATE *OCT - 1 1984*

CONDITIONS OF APPROVAL, IF ANY:

water. Set slips and WOC. Drill out cmr to 4255'. Reverse
hole clean. Load hole with fresh water and pres. test seq.
to 1500 psi. POH. Run logs and shut-in pending
completion.

NOV 28 1984

C.C.D.
HOOD OFFICE