

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-28004

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
L-4634

7. Lease Name or Unit Agreement Name
DIVINE '29' STATE

8. Well No. 1

9. Pool name or Wildcat
EUMONT YATES 7-RIVERS

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator
PENROC OIL CORPORATION

3. Address of Operator
P.O. Box 5970, HOBBS, NM 88241-5970

4. Well Location
Unit Letter O : 660 Feet From The SOUTH Line and 1980 Feet From The EAST Line
Section 29 Township 20 Range 36 NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3618.6' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well data: 8 5/8", 24" @ 393' w/ 220 SXS. CMT. CIRC. TO SURFACE
5 1/2", 14" @ 3959' w/ 750 SXS. CMT CIRC. TO SURFACE
PERFS: 3822' - 3950' (23pf, 136 holes)

Plan to rig up well servicing unit. Pull & LD rods & pump. (May have to fish/strip rods because of paraffin). TOH w/ tbg. Run & set 5 1/2" CIAP @ 3750'. Spot 2 SXS. cmt on top. Circulate hole w/ gelled brine. Spot 25 SXS. plug from 1800-1900'. Pull up & spot 25 SXS. plug 350-450'. spot 10 SXS. @ surface. Install dry hole marker. Cut anchors. Clean up location. Move salvage to yard.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stephen Y. Merchant TITLE PRESIDENT DATE 3/16/92
TYPE OR PRINT NAME M. Y. (Merch) Merchant TELEPHONE NO. (505) 397-3596

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE ADVISED 24 HOURS PRIOR TO THE PLUGGING OR PLUGGING OPERATIONS AND TO BE APPROVED.

MAR 16

RECEIVED

MAR 16 1992

OCD HOBBS OFFICE